

TOWNSHIP 24 RANGE 03 POINT IDENTIFIER # 300200

PRIMARY CORNER DESCRIPTION Cor Secs 28, 29, 32, & 33

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars under contract #152, dated June 3, 1871 - (DCSO records Vol. 7 Page(s) 2956)  
-----  
Set post cor. to secs. 28, 29, 32 & 33 from which  
A fir, 10" dia., bears N.55°E., 13 lks.  
A fir, 7" dia., bears S.35°E., 22 lks.  
A fir, 11" dia., bears S.22°E., 12 lks.  
A fir, 6" dia., bears N.76°W., 14 lks.

Fd. & used on GLO survey by L.H. Wheeler under Contract No. 467 dated April 7, 1883 (DCSO records Vol. 7 Page(s) 2997-8)

Douglas Co. Surveyors Office - James W. Byron, Deputy -  
Witnesses: G. Welker & J. Fee - For: Roseburg Lumber Co. -  
Oct. 29, 1956 - C.S. File 47/132  
-----  
Found - Orig. SE BT scribing good, now 14" snag.  
SW orig. BT now 30" alive & good condition, shows old blaze, I do not open.  
NW orig. BT base of stump only.  
NE orig. BT stump only. I open at base, scribed BT.  
Position of corner fixed by using distances (rec.)  
SE orig. BT bears S.30°E.  
NE orig. BT bears N.53°E.  
SW orig. BT bears N.46°W.  
NW orig. BT bears N.72°W.  
Set brass cap at corner mkd: 29|28 T24S R3W County Surveyors  
32|33 Office 1956  
Rescribe 30" Fir bears S.41°30'W., 7.9 ft. S32 T24S R3W CS BT  
Bl & Sc. 18" Cedar bears N.40°19'W. 41.0 ft S29 T24S R3W CSBT  
10" W.Fir bears N.38°57'E. 58.41 ft. S28 T24S R3W CSBT  
10" W.Fir bears S.53°E., 26.7 ft. S33 T24S R3W CSBT  
Note - See file for sketch

Daniel Baker - Weyerhaeuser Co. - 12/15/94 - M 121 - 58 A&B  
-----  
Found - Douglas county brass cap dated 1956  
10" W.Fir, S.53°E. 26.7', rec. S.53°E. 26.7 - 1956  
10" dead W.Fir N.39°E. 58.4' rec. N.39°E. 58.41' 1956  
New BT's- 11" fir, S.30°W. 15', scribed "T24S R3W S32 BT"  
6" fir, N.65°E. 5.2', scribed "T24S R3W S28 BT"  
9" fir, N.24°W. 11.9', scribed "T24S R3W S29 BT"  
6' Fencepost 1' north.

Found OK by D. Edwards, Dec. 2004 - M147-4

continued next page

PRIMARY CORNER DESCRIPTION Cor. Secs. 28, 29, 32, & 33

Alias	Description

Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and Jeff Lorsung - 12/4/2025 - C.S. File 67/61-46

-----  
Found - 2½" D.C.S.O. brass cap proj 14".  
Sawn, rotted 28"x 4½ ft. W. fir stump S.53°E. 26.7 ft.  
fully healed single blaze.  
Sawn 18" x 5½ ft. D. Fir stump S.28½°W. 16.7 ft.  
(Rec. S.30°W. 15.0 ft.) fully healed double  
blaze 3½" mag nail added right side center.  
Sawn 14" x 1½ ft. D. fir stump N.60°E. 5.3 ft. (Rec  
N.65°E. 5.2 ft.) fully healed double blaze. Add  
3½" mag nail top center.  
Sawn 18" x 1½ ft. D. fir stump N.33°W. 12.6 ft.  
(Rec N.24°W. 11.9 ft) fully healed single blaze.  
Add 3½" mag nail top center.

Fence post 1° north.  
New - 19" x 1½ ft. D. fir stump S.4°E. 6.0 ft. 3½" mag  
nail top center.

Notes - Mon approx. 240 ft. west of gravel road.  
Area burnt 9/2020.  
Mon on gentle S.W. slope in young fir reprod.

Compass decl. 14¼°E.  
O CRS COORDINATE SYSTEM  
COTTAGE GROVE-CANYONVILLE ZONE  
N. 223285.520 E.233790.712