

TOWNSHIP 24 RANGE 03 POINT IDENTIFIER # 300240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 28 & 29

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

<p>GLO survey by W.H. Byars under contract #152, dated June 3, 1871 - (DCSO records Vol. 7 Page(s) 2956)</p> <p>-----</p> <p>Set ¼ sec. post from which A cedar, 10" dia., bears N.80°E., 5 lks. A fir, 14" dia., bears N.35°W., 31 lks.</p>
<p>Douglas Co. Surveyors Office - Vernon "Ray" Tracy - - April/May 1968 - C.S. File 54/27-153</p> <p>-----</p> <p>Reported as not found. Logged many years ago.</p>
<p>Daniel Baker - Weyerhaeuser Co. - 12/15/94 - M 121-58 A&amp;B</p> <p>-----</p> <p>Set - 1¼"x36" iron pipe with 2½" Brass cap (mkd) dated 1994 T24S R3W ¼ S29 S28 PLS 1978 1994 12" fir, N.80°W. 11.3', scribed "¼ S29 BT" 15" fir, N.30°E. 18.7', scribed "¼ S28 BT" 14" fir, S.82°E. 11', scribed "¼ S28 BT" 10" fir, S.32°W. 13.5', scribed "¼ S29 BT" 6" Carsonite post 1' north.</p>
<p>David Edwards - For: Roseburg Resources Co. - 12/2004 - M 147-4</p> <p>-----</p> <p>Found - Brass cap All BTs are stumps 6' carsonite post 1' north Set - 6' steel posts 2' South and West.</p>
<p>Douglas Co. Surveyors Office - Crew: Stephen Flause &amp; Jeff Lorsung- 8/22/2024 - C.S. File 67/58-56</p> <p>-----</p> <p>Found - 2½" brass cap (properly mkd) on 1¼" iron pipe up 6". Singed-rotted 13"x2 ft. Fir stump N.86°W., 11.5 ft (rec. N.80°W. 11.3 ft) fully healed double blaze. Rotted very burned 12"x5 ft. stump N.24°E., 18.7 ft. (rec. N.30°E.) blaze gone. Burned rotted 14"x6 ft. Fir stump S.88°E., 11.0 ft. (rec. S.82°E.) fully healed double blaze. Burned rotted 12"x6 ft. Fir stump S.26°W., 13.5 ft. (rec. S.32°W.) fully healed double blaze. Continued next page</p>

TOWNSHIP 24 RANGE 03 POINT IDENTIFIER # 300240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 28 & 29

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

6' carsonite post 1' north.  
6' steel post 2' South and west.  
Note - All distances to "W" nail in tree faces.  
Area burnt 9/2020  
Compass decl. 14¼°E.  
Mon on steep NNW slope in partly burned reprod ridge  
top approx 70 ft South.  
Gravel road approx. 140 ft. North.  
Oregon Coordinate Reference System  
Cottage Grove - Canyonville Zone  
N 225979.417 E 233709.994