

TOWNSHIP 24 RANGE 03 POINT IDENTIFIER # 400100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 33 & 34; 3 & 4 of T25-3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - W.H. Byars, Under Contract #152 dated June 3, 1871  
(DCSO records, Volume 7 Page 2945)

-----  
Set post cor. to secs. 3, 4, 33, and 34, from which  
A Fir 30" dia. bears N.52°E., 10 lks. dist.  
A Fir 8" dia. bears S.50°E., 46 lks. dist.  
A Fir 36" dia. bears S.5°W., 56 lks. dist.  
A Fir 24" dia. bears N.40°W., 56 lks. dist.

A. Boyer, Deputy Co. Surveyor - Wit: Ted Shellabarger and Joe  
Murphy - April, 1940 - Vol. 4 Page 80; C.S. File 35/38

-----  
Set cor. from old original BTs as follows:  
A Fir 30" bears N.52°E., 10 lks.  
A Fir 8" bears S.50°E., 46 lks.  
A Fir 36" bears S.5°W., 56 lks.  
A Fir 24" bears N.40°W., 56 lks.  
Marked new BT:  
A Fir 4" bears S.31°E., 13.0 ft.

GL0 resurvey by Norman D. Price under Special Instructions  
dated April 5, 1940 (DCSO records, Volume 27 Page 11535)

-----  
The original cor. of secs. 3, 4, 33 and 34, the locus of  
which has been perpetuated by the Co. Surveyor's Fir post, 4  
ft. long, 4" square, firmly set, mkd. S 34 on NE., S 3 on  
SE., S 4 on SW., and S 33 C S on NW face.

At point for corner, set an iron post, 3 ft. long, 2" dia.  
28" in the ground, with the Co. Surveyor's marked stake  
deposited at the base, for cor. of secs. 3, 4, 33, and 34,  
with brass cap marked:

T24S R3W  
S33|S34  
S4S3  
T25S  
1943

from which

A Fir 50" dia. bears N.58°E., 13 lks., mkd. on bark S 34  
T24S R3W BT. I re-blaze and re-mark this old  
bearing tree T 24 S R 3 W S 34 BT.

A fir stump 16" dia. bears S.55°E., 50 lks., on which no  
marks remain. (Old BT)

A Fir 48" dia. bears South 54 lks., mkd. on bark S 4  
T25S R3W BT. I re-blaze and re-mark this old  
bearing tree T 25 S R 3 W BT. (Old BT)

A Fir stub, 38" dia. bears N.44°W., 49 lks., mkd. on  
bark S 33 T 24 S R 3 W B T. (Old BT)

continued next page

TOWNSHIP 24 RANGE 03 POINT IDENTIFIER # 400100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 33 & 34; 3 & 4 of T25-3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A Fir 5" dia. bears S.29½°E., 20 lks., mkd. T 25 S R 3 W  
S 3 C S B T. (Co. Surveyor's BT)  
A Fir 6" dia. bears N.39 3/4°W., 50 lks., marked T 24 S R  
3 W S 33 C S B T. (Co. Surv. BT)

Doug. Co. Surveyors Office - Vernon Tracy; Jack Heritage  
Sept. 1966 - C.S. File 54/27-133

-----  
Found - 1943 GLO brass cap.  
50" now 54" Fir N.58°E., 8.3 ft. alive, shows good  
scar & old bark scribe.  
48" now 51" Fir South 35.6 ft. Alive, shows good  
scar.  
38" Fir stub N.44°W., 32.3 ft., very badly decayed  
5" now 7" Fir S.29½°E., 13.2 ft. alive, shows good  
scar.  
6" now 8" Fir N.39 3/4°W., 33.0 ft. alive, shows  
good scar.

Due to larger Firs being marketable trees, we mark new BTs:  
8" D.Fir N.13°E., 17.5 ft. mkd: T24S R3W S34 CSBT  
7" Live Oak S.46°W., 29.2 ft. mkd: T25S R3W S4 CSBT  
This corner lies on W. slope approx. 75 ft. W. of rock bluff,  
40 ft. high.

Found and Used, BLM resurvey by Rogers, Bedell and Peterson  
Group # 1386 - June 1987-Sept. 1988 (DCSO records, Volume 48  
Pages 18478-79)