

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 9 & 10

Alias	Description
Alias	Description
Alias	Description
Alias	Description

<p>GLO survey by W.H. Byars under contract #152, dated June 3, 1871 - (DCSO records Vol. 7 Page(s) 2952)</p> <p>-----</p> <p>Set ¼ sec. post from which A yew, 7" dia., bears N.20°E., 16 lks. A hemlock, 24" dia., bears N.80°W., 12 lks.</p>
<p>Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - E. West - Sept. 1967- C.S. File 54/27-82</p> <p>-----</p> <p>Found - Orig. 7" now 9" Yew, alive, N.20°E., 10.6 ft., bent over &amp; blaze rotted away, no scribe found. Orig. 24" now 37" Hemlock, alive, N.80°W., 7.9 ft., open &amp; find scribe reverse. We use face measurements on OBTs</p> <p>Set - Brass cap at cor. mkd: County Surveyors T24S R3W Office 1967 ¼ S 9 S 10</p> <p>New BTs- 6" Hemlock S.58°W., 22.6 ft., mkd: ¼ S9 CS BT 14" Hemlock S.64°E., 25.1 ft., mkd: ¼ S10 CS BT</p> <p>Note - This corner lies westerly slope in small stand of old growth timber.</p>
<p>Weyerhaeuser Co., C. Volz - Witnesses: L. Wilson &amp; L. Warren - Jan. 13, 1969 - C.S. File 53/111-31</p> <p>-----</p> <p>Found - DCSO brass cap - <u>set yew post</u> on east side of cap. 37" Hemlock, N.85°W., 7.3 ft., scribing visible, face chopped out. 9" Yew, N.20°E., 10.6 ft., bent over face rotted. Scribing not visible. 6" Hemlock S.58°W., 22.6 ft., scribing visible. 14" Hemlock S.64°E., 25.1 ft. scribing visible. Added "W" nail &amp; Plate to 37" hemlock &amp; 14" hemlock.</p>
<p>Robert Cook - For: Weyerhaeuser Co. - 12/2010 - M161-57</p> <p>-----</p> <p>Found - 2½" Douglas Co. brass cap down 1" with monel pipe riser on SE side. I set steel post south 0.8'. 27" Hemlock snag N.80°W. 7.92 ft &lt;N.80°W. 12 lks&gt; to face w/scribing visible "¼S" on plain open face. 15" D.Fir N.62°E., 16.5 ft. with healed face &amp; tag. 16" D.Fir N.50°W., 23.3 ft. with healed face &amp; tag.</p> <p>New - 15" D.Fir S.5°E., 29.8 ft. scribed "¼S10" above "BT" 11" D.Fir S.28°W., 20.4 ft. scribed "¼S9" above "BT"</p>