

TOWNSHIP 24 RANGE 04 POINT IDENTIFIER # 040040

PRIMARY CORNER DESCRIPTION SSE Cor. Wm. Hanna DLC #40

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

DLC Survey by - Dennis Hathorn, under contract dated Sept 1856 (DCSO DLC records Pg 149)

An Oak, 24" dia., bears N.89°W., 1015 lks.
An Oak, 12" dia., bears S.88½°W., 1020 lks.

Douglas Co. Surveyors Office -Milo E. Godfrey, Deputy Co. Surveyor - Vernon Tracy - Mike Stone - May 1963 - C.S. File 53/9-67

Found - 36" B.Oak, N.89°W., 669.9', opened scar & fd. good scribing.
No trace of the SW tree.
Position for corner falls in field.
Set - Witness corner 6 ft. West of corner. Brass cap mkd:
COUNTY SURVEYORS OFFICE 1963 T24S R4W ____| 6 FT.
E TO CORNER.
22" W.Oak N.53½°W. 487.4', mkd: WC S SE DLC 40 CS BT
Witness corner lies 1 foot East of N.& South fence line.