

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 32 & 33

Alias	Description

Original - Gordon & Gardner, Contract #52 dated Feb. 1855 (DCSO records Vol. 7 Page(s) 3042)

Set ¼ sec. post from which
 An Ash 12" dia., bears S.5'W., 211 lks.
 A W.Oak, 15" dia., bears N.25°W., 240 lks.

Milo E. Godfrey, Deputy Co. Surveyor - Vernon Tracy - Mike Stone - May 1963 - C.S. File 53/9-78

Found - 32" W.Oak, showing faint scar. Inside found good "¼S" scribe & reverse of scribe. This tree faced good for bearing, called for N.25°E.
 No trace of other BTs.
Set - Brass cap at cor. mkd: COUNTY SURVEYOR'S OFFICE 1963
 T24S R4W ¼ S32/33
 7" W.Oak, N.75°E., 147.3' mkd: ¼ S33 CS BT.
 13" Ash, S.24°W., 273.3' mkd: ¼ S32 CS BT.

BLM dependent resurvey by James E. Jelly, Cadastral Surveyor, under Group #979, surveyed May/Sept. 1979 (DCSO records Vol. 42 Page(s) 16393)

The ¼ cor. perpetuated and recorded by Godfrey in 1963, determined at recorded bearing and distance from the remaining orig. BT:
 A W.Oak, 37" dia., bears N.25°E., 240 lks., with fragmentary scribe marks visible on open blaze.
and bearing trees mkd. by Godfrey:
 A W.Oak, 9" dia., bears N.75°E., 223 lks., with healed blaze.
 An Ash, 22" dia., bears S.24°W., 414 lks., with healed blaze.
At corner point
Set an iron post, 28" long, 2½" dia., 40" in the ground, the top 12" below the surface, with brass cap mkd:
 T24S R4W
 ¼
 S 32 | S 33
 1979
Set a steel fence post alongside iron post.

Fd & used by BLM dependent resurvey by Lance J. Bishop & Wayne L. Rogers, Cadastral Surveyors, under Group #1178, surveyed Sept. 1983(DCSO records Vol. 46 Page(s) 17810-11)