

TOWNSHIP 24 RANGE 04 POINT IDENTIFIER # 500240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs , 26 & 27

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

<p>Original - Gordon &amp; Gardner, Contract #52 dated Feb. 1855 (DCSO records Vol. 7 Page(s) 3036)</p> <p>-----</p> <p>Set 1/4 sec. post from which A Laurel, 18" dia., bears N.75°E., 38 lks. A Fir, 36" dia., bears S.57°W., 32 lks.</p>
<p>O.F. Thiel - For: S.S. Schell - Oct. 1927 - FB 116 PG 26</p> <p>-----</p> <p>Found stumps of NE tree &amp; SW (a Fir) standing, remarked both trees.</p>
<p>Douglas Co. Surveyors Office -Milo E. Godfrey, Deputy Co. Surveyor - Vernon Tracy - Mike Stone - June 1963 - C.S. File 53/9-88</p> <p>-----</p> <p>Found - 36" Fir snag, old &amp; rotten, S.57°W., 21.1'. Portions of bark scribing vis. "1/4" &amp; "B" Stump hole with small fragments of rotten Laurel wood, N.75°E., 25.1', not enough left to find any markings.</p> <p>Set - Brass cap at cor. mkd: COUNTY SURVEYORS OFFICE 1963 T24S R4W 1/4 S27/S26 11" B.Oak, N.14°E., 24.0', mkd: 1/4 S26 CS BT. 8" D.Fir, N.46°W., 16.8', mkd: 1/4 S27 CS BT.</p> <p>Corner lies in fence corner, fences South &amp; East from corner.</p>
<p>Fd. &amp; used in BLM dependent resurvey by Charles E. Akin, Jr., Cadastral Surveyor, under Group #793, surveyed Aug. 1972 (DCSO records Vol. 36 Page(s) 14858)</p>
<p>Fd. &amp; used in BLM dependent resurvey by Lance J. Bishop &amp; James L. White, Cadastral Surveyor, under Group 1233, surveyed Oct. 1984/Jan. 1985(DCSO records Vol. 47 Page(s) 18024)</p>
<p>Fd. Ok by H.Christensen - 12/95 - M 123-21 Fd. OK by Harvey Christensen, 9/2001 - M 138-80 FD. ok by Kris DeGroot, 8/2008 - 2008-0061A-G</p>
<p> </p>