

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 10 & 11 (WC)

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - Oscar F. Thiel, Contract #658, May 1896 (DCSO records Vol. 7 Page(s) 3067)

Set a Fir post 3' long, 3" sq. 24" in the ground for ¼ sec. cor. mkd: ¼ S, on W face from which

A Fir, 8" dia., bears S.64°W., 16 lks., mkd: ¼ S BT.

A Fir, 10" dia., bears N.56°E., 19 lks., mkd: ¼ S BT.

This corner stands 350' below top of ridge.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy Co. Surveyor - Vernon Tracy - Mike Stone - Mar. 1963 - C.S. File 53/9-37

Found - Recently broken Fir snag, now 24", N.56°E., 12.5', good scribing.

22" Fir, uprooted, not recent, S.64°W., 10.4', shows good scar.

Position for corner falls in creek.

Set Wit. cor. 40' North.

Set - Brass cap at cor. mkd: COUNTY SURVEYOR'S OFFICE 1963

T24S R4W WC ¼ S10/S11 CORNER 40 FT. S.

13" D.Fir, S.74°E., 39.6', mkd: WC ¼ S11 CS BT.

21" D.Fir, S.32°E., 26.3', mkd: WC ¼ S11 CS BT.

No trees available except in SE quad.

Ford-Ness-Fassbender, Steven Ness - 6/25/97 - C.S. 65/15-4B

Found - 2½" DCSO Brass cap on a 1¼" I.post, top 14" above ground for witness corner (actual corner position is south 40.0' in creek) the following BT's reference the witness corner.

21" D.Fir, S.72°48'E., 39.4', face healed.

20" D.Fir, S.30°34'E. 26.1, face no healed, scribing "WC ¼ S11 CS BT" visible. snag is about 30' tall.

New BT - 9" D.Fir, N.5°09'W., 19.5', scribed "X" on chest high face, scribe "BT" on low face.

The corner is in the NW corner of a recently harvested BLM clear-cut unit. It is + or - 880' east of ridge top.

BLM dependent resurvey by Wayne L. Rogers, under Group #1834 surveyed April 1997 - (DCSO records Vol. 52 Page(s) 20181)

The ¼ sec. cor. of secs. 10 & 11, determined at record distance from the remains of the original BTs and the witness corner (reference monument) established by Godfrey in 1963, from which the remains of the original bearing trees

continued next page

TOWNSHIP 24 RANGE 04 POINT IDENTIFIER # 500540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 10 & 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A fir snag, 26" diam., bears N.62 3/4°E., 19 lks., with fragmentary scribe marks and a chaining notch visible on an opened blaze. (Record, N.56°E.)

A roothole, bears S.64°W., 16 lks., with a downed fir alongside, 20" diam., no marks or scar visible on decayed trunk.

and a witness corner (reference monument) established by Godfrey, in 1963

An iron post, 1 1/4" diam., firmly set, projecting 10" above ground bears N.1°04'00"E., 0.606 chs. (40.00 ft.), with brass cap mkd. COUNTY SURVEYORS OFFICE T24S R4W 1/4 S10 S11 WC COR 40 FT S 1963, from which:

A fir, 23" diam., bears S.74°E., 60 lks., with healed double blaze

A fir snag, 21" diam., bears S.32°E., 40 lks., w/scribe marks 1/4 S11 CS BT visible on open double blaze.

and a new bearing tree

A fir, 10" diam., bears N.7 1/2°W., 29 lks., mkd. X BT.

The corner point is located in the edge of a creek where it is impractical to set a permanent monument.