

PRIMARY CORNER DESCRIPTION E 1/16 Cor. Secs. 2 & 11

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Original - Gordon & Gardner, Contract #52 dated Feb. 1855 (DCSO records Vol. 7 Page(s) 3031)

Ascend South slope of inaccessible mountain, set post from which

- A Redwood, 8" dia., bears N.66°W., 7 lks.
- A Redwood, 5" dia., bears S.3°E., 3 lks.

Fd. & used by Oscar F. Thiel, Contract #658, May 1896 (DCSO records Vol. 7 Page(s) 3061)

Wilford Haines - Leo Martin - Jan. 1957 - M 4-16

Found - 5" Cedar (Redwood) S.3°E., 3 lks., (snag.)
8" Cedar (Redwood) N.66°W., 7 lks., (on ground.)

Set - 1"x36" iron ⊥ rod w/brass cap attached & inscribed

- "Survey point - Wilford N. Haines No. 239"
- 24" Fir, S.68°E., 43.5'. (WC S11 BT)
- 16" Fir, N.76°W., 28.0'. (WC S11 BT)

GLO dependent resurvey by Lynn M. Roseberry, Cadastral Surveyor, Group #349, surveyed Aug/Sept 1957 (DCSO records Vol. 28 Page(s) 12103)

The E 1/16 cor. perpetuated with an angle iron, 36x1x1 ins., firmly set 30" in the ground, with brass cap mkd: Wilford N. Haines, 239, survey point, Drain, Ore." from which the remains of OBTs:

- A stump hole, N.66°W., 7 lks., I found a turned out Cedar, 19" dia., 20 lks., South, marked R4WC on opened blaze. (Record calls for a Redwood)
- A Cedar stump, 8" dia., bears S.3°E., 3 lks., dist. marked S11 WC on opened blaze. (Record calls for a Redwood)

and trees marked by Haines in 1957

- A Fir, 20", N.84°W., 42 lks., bark scribed WC S2 BT.
- A Fir, 25", S.73°E., 63 lks., bark scribed WC S11 BT.

At the corner point

Set an iron post, 30" long, 2" dia., 24" in the ground, with brass cap mkd:

S 2
E 1/16 S 11
1957

from which

- A Cedar, 20" dia., bears N.37½°W., 18 lks., mkd: E 1/16 S2 BT.
- A Cedar, 16" dia., bears S.16 3/4°W., 2½ lks., mkd: E 1/16 S11 BT.