

PRIMARY CORNER DESCRIPTION Cor Secs 1, 2, 11, & 12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Oscar F. Theil, Contract #658, May 1896 (DCSO records Vol. 7 Page(s) 3061-62)

A point 120' below top of ridge, I set an Alder post 3' long 4" sq. 24" in the ground for cor., mkd: T24S S1 on NE; R4W S12 on SE; S11 on SW and S2 on NW faces with 1 notch on E and 5 notches on S edges from which

A Fir, 8" dia., bears N.32½°E., 11 lks., mkd: T24S R4W S1 BT.

A Fir, 30" dia., bears S.68½°E., 18 lks., mkd: T24S R4W S12 BT.

A Fir, 24" dia., bears S.44°W., 29 lks., mkd: T24S R4W S11 BT.

A Fir, 16" dia., bears N.12°W., 93 lks., mkd: T24S R4W S2 BT.

Wilford Haines & Leo J. Martin - Jan. 1957 - M 4-16

Found all BTs except the NW BT.
Set an 1"x36" ⊥ rod with brass cap attached and inscribed "Survey point Wilford N. Haines #239"

GLO dependent resurvey by Lynn M. Roseberry, Cadastral Surveyor, Group #349, surveyed Aug/Sept 1957 (DCSO records Vol. 28 Page(s) 12100)

The cor. perpetuated by a cedar stake, 18" long, 1½" sq., firmly set 6" in the ground, from which the orig. BTs:

A Fir, 18" dia., bears N.23½°E., 11 lks., with scribe marks 24S 4 1 BT vis. on partly opened blaze. (Rec. bearing, N.32½°E.)

A Fir, 36" dia., bears S.66°E., 18 lks., with a healed blaze. (Rec. bearing S.68½°E.)

A Fir, 32" dia., bears S.47°W., 29 lks., with scribe marks 11 vis. on partly opened blaze. (Rec. bearing S.44°W.)

A Fir, 30" dia., bears N.12°W., 93 lks., with a healed blaze.

At the corner point
Set an iron post, 30" long, 2" dia., 24" in the ground, with brass cap mkd:

T24S R4W	
S 2	S 1
S 11	S 12
1957	

Reset the cedar stake alongside the iron post.

TOWNSHIP 24 RANGE 04 POINT IDENTIFIER # 600600

PRIMARY CORNER DESCRIPTION Cor Secs 1, 2, 11, & 12

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas Co. Surveyors Office -Milo E. Godfrey, Deputy Co. Surveyor - Vernon Tracy - Mike Stone - July 1963 - C.S. File 53/9-104

Found - Brass cap set in 1957, good condition
36" Fir, S.66°E., 11.9', alive & standing, shows good scar.
30" Fir, N.12°W., 61.4', alive & standing, shows scar.
The NE & SW trees are both uprooted & down, probably down by Oct. 1962 windstorm.

New BTs- 27" D.Fir, N.66°E., 38.6', mkd: T24S R4W S1 CS BT.
5" W.Fir, S.18°W., 41.2', mkd: T24S R4W S11 CS BT.

Les Roberts - For: Seneca Jones Timber Co. - Oct. 1999 - M133-54

Found - 1957 GLO iron pipe & brass cap.
36" Fir snag, S.66°E., 11.9' (scar vis). 1896 BT.
36" Fir, N.12°W., 61.4' (scar vis). 1896 BT.
12" W.Fir (downed) S.18°W., 41.2' (No marks) 1963 BT
32" Fir N.66°E., 38.6' (scar vis) 1963 BT

Set - 8" Alder, S.38°W., 18.3' (scribed/metal Washer /painted red)
14" Hemlock, S.17°E., 29.1' scribed/metal Washer /painted red)

Fd. Ok by D. Edwards, 5/2006 - C.S. File 65/57-9