

PRIMARY CORNER DESCRIPTION Center West 1/16 Sec. 25

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Resurvey by C. Albert White & Norman J. McDonald, Cadastral Surveyors, under Group #'s 243, 350, & 513, surveyed April/July 1963 - (DCSO records Vol. 32 Page(s) 13469)

-----  
Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd:

W 1/16  
C \_\_\_\_\_ C  
S 25  
1963

from which

A forked Fir, 30" dia., bears S.18 3/4°W., 40 lks., mkd: CW 1/16 S25 BT.

A Fir, 26" dia., bears West, 9 lks., mkd: CW 1/16 S25 BT.

-----  
Douglas Co. Surveyors Office - Randall W. Smith - Stephen J. Flause - 8/9/1990 - C.S. File 64/10-2

-----  
Found - 3½" dia., 1963 BLM brass cap on a 2½" O.D. iron pipe on edge of cut bank, protruding 2" above ground. 26" now 26" dia., 6' high D.Fir stump with a fully healed single blaze bears West, 5.9', agrees w/rec. 1963 BLM BT

30" now 24" dia., 5' high D.Fir stump with a fully healed single blaze on easterly fork of a double trunked stump bears S.18 3/4°W., 26.4' to easterly trunk, agrees w/rec.

New BTs- 7" dia., D.Fir, double blazed and scribed "CW 1/16 S25 CS BT" bears S.42°E., 15.4'

5/8" x 31" long iron rod with a DCSO alum. cap stamped "BO-1 1990" is set. It protrudes 5" above ground, bears South, 10.0'.

Corners lies at edge of top of a steep cut bank on south side of road. approx. 300 ft. from end of road.