

TOWNSHIP 24 RANGE 05 POINT IDENTIFIER # 600240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 25 and 26

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Robert Elder, under Contract #31 dated April 7, 1853 (DCSO records Vol. 8 Page(s) 3091)

Set 1/4 sec. post, from which
A W.Oak 5" dia., bears S.52°E., 144 lks.
An Ash 12" dia., bears N.65°W., 65 lks.

G.G. Stewart, Deputy - Wit: T.J. Medley; R.R. Clarke; Roy Medley - Jan. 16, 1922 - Vol. 3 Page 110 (and "old" corner book, page 44)

Set squared Chitem wood post with mound of rocks around it.

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, Milo Godfrey, S.A. Bilow - April 3, 1959 - C.S. File 49/124-4

Found - Part of rock mound, rocks placed in a circle.
W.Oak tree, now 17", S.52°E., 95 ft. This tree showed scars. Opened tree and found it had been opened about 60 years ago. Center rotted out.
Ash tree, now 28", N.65°W., 42.9 ft. This tree had been reblazed. Scribe marks visible in still open upper and lower faces approx. 3" inside present bark. Probably Stewart's scribing. Through an opening in the NE face, I could see that the entire center of the tree has rotted away.

At corner set iron pipe with brass cap mkd:
County Surveyors Office
T 24 S R 5 W
1/4 S26 | S25
1959

Built mound of rocks around corner.
Blaze and scribe the following trees:
17" W.Oak N.48°E., 4.6 ft. mkd. 1/4 S25 CS BT.
10" W.Oak N.33°W., 29.3 ft. mkd. 1/4 S26 CS BT.
Fence corner bears East 23.3 ft., fences N & E.
Corner is 9 ft. West of small creek flowing S.15°E.

Found OK by C. Sweeden, Feb. 1998 - M 124-72
Fd. as per M124-72, 3/2016 - M170-60