

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 19 and 30

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #577, dated July 18, 1891 (DCSO records Vol. 8 Page(s) 3162)

A Maple 14" dia., which I marked ¼ S on North side for ¼ sec. corner, from which
 A W.Fir 26" dia., bears N.38°W., 75 lks. dist. mkd. ¼ S BT
 A W.Fir 15" dia., bears S.78°15'W., 160 lks. dist. mkd. ¼ S BT.

BLM dependent resurvey by Joseph S. Gawron under Group #464 surveyed May/June 1962 (DCSO records Vol. 31 Page(s) 13119)

The ¼ sec. cor., monumented by a Maple 16" dia., with chopped and exposed faces on the N. and S. sides. This position is harmoniously related to existing original corners, has long been recognized as the corner by adjacent land owners, and is accepted as the best existing evidence of the original corner tree:
from which a new bearing tree and reference monument
 An iron post, 30" long, 2½" dia., set 24" in the ground, and in a mound of stone, 5 ft. base to top, for a reference monument, bears North 4 lks. dist., with brass cap mkd. ¼ S19 RM 1962, and an arrow pointing to the true corner.
 A Fir 9" dia., bears S.73°W., 128 lks. dist., mkd. ¼ S30 BT.

Gary T. Smither - I.P. Timberlands - Oct. 1995 - M 122-70

Mon. Fd. - Corner tree (maple) is gone
 Brass cap reference monument 4 Lks. North
Bt's Fd. - 19" D.Fir, S.73°W., 128 lks., wiht healed face and bearing tree tag.