

TOWNSHIP 24 RANGE 06 POINT IDENTIFIER # 200240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 29 and 30

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Robert Elder and Henry Gile, Deputy Surveyors, under Contract #31 dated April 7, 1853 (DCSO records Vol. 8 Page(s) 3157)

Set ¼ sec. post, from which
 A Fir 8" dia., bears N.19°E., 15 lks. dist.
 A Fir 8" dia., bears S.35°W., 27 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, Milo Godfrey; S. Bilow - April 18, 1958 - C.S. File 49/83-12

Found - Orig. 8" now 24" snag, N.19°E., 9.9 ft. This BT partly rotted. I open & find good scribing "BT ¼"
 I find no trace of orig. SW BT.

Set Brass cap at cor. mkd: County Surveyors Office
 T 24 S R 6 W
 ¼ S30 | S29
 1958

New BTs -7" R.Fir bears N.84°W., 12.0 ft. scribed ¼ S30 CSBT
 8" R.Fir bears N.65°E., 16.4 ft. scribed ¼ S29 CSBT
Sketch in C.S. File that shows relationship of cor. and fenceline.

David Edwards - Crew: Brant Miller & Eric Sprinkle - 7/2016 - C.S. File 65/93-25

Found - Standard DCS brass capped iron pipe from 1958 ren.
 19" Fir with healed blazes and tag bears N.65°E., 16.4'

 The N.84°W., Fir is a stump. The 1958 DCS Fir stump is 18" in dia. & 12.0' dist. from the brass cap.

BTs fd with 2003 DCS tags and healed blazes not of record -
 A 12" dia. Fir bears S.20°W., 14.3 ft.
 A 16" dia. Fir bears S.77°W., 28.8 ft.

Set - A ft steel post 2 ft. West
 Compass decl. 15°E.