

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 7 and 8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #577, dated July 18, 1891 (DCSO records Vol. 8 Page(s) 3187)

Set sand stone 20x12x6 ins., 5" in the ground, for ¼ sec. cor., mkd. ¼ on W. face, from which
A Fir 45" dia., bears N.8°15'E., 18 lks. mkd. ¼ S BT.
A Fir 18" dia., bears N.35°W., 48 lks. dist. mkd. ¼ S BT.

Douglas Co. Surveyors Office - John M. Powell, J. Heritage, W. Penley, crew - Sept. 2, 1970 - C.S. File 52/102-12

Found - 20x12x6 stone, lying on ground mkd. "¼".
45" now 47" D.Fir N.8°E., 11.9 ft., shows good scar.
18" now 28" D.Fir N.35°W., 31.7 ft., faint bark scribe "¼".

Set Brass cap at cor. mkd: County Surveyors Office
T 24 S R 6 W
S 7 | S 8
1970

Reblazed and rescribe:
28" D.Fir N.35°W., 31.7 ft. mkd. ¼ S7 CS BT.

Douglas Co. Surveyors Office - Randall Smith and Stephen Flause, crew - Aug. 29, 1989 - C.S. File 64/1-18

Found - 1970 DCSO 2½" dia. brass cap on a 1¼" O.D. x 30" long I.P. out of ground, up against base of orig. NE BT.
Fractured stone, largest piece measures 15"x9"x5" at position of corner, no marks found. (orig. was 20"x12"x6", 15" in ground & mkd. ¼ on W. face.)
45" now 46" dia. D.Fir with a fully healed blaze, bears N.8¼°E., 11.9 ft. (agrees w/rec.)
18" now 36" dia., 4 ft. high D.Fir stump with a metal cap on top. All bark gone from stump. A partially healed single blaze with scribing visible "4" bears N.35°W., 31.7 ft. (Orig. BT, rescribed in 1970)

Position of corner determined from bearings and distances to orig. BTs. 1970 DCSO BC/IP is set at referenced position and now protrudes 2" above ground, a mound a stone is set along northerly side of brass cap. The marks "RESET 1989" are added.

New BTs -6" dia. D.Fir double blazed and scribed "¼ S7 CS BT" bears N.51°W., 51.0 ft.
8" dia., D.Fir double blazed and scribed "¼ S8 CS BT" bears S.01°E., 17.0 ft. (Cont. Next Page)

TOWNSHIP 24 RANGE 06 POINT IDENTIFIER # 200540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 7 and 8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Cor. lies on a steep North slope on a N-S cut line, new clear cut is to the West. Cor. is approx. 150 ft. NE of landing at end of road.

Jerry Estabrook - Bruce Webster - 2/21/2004 - C.S. File 65/49-15

Condition report only

- Found - 2½" brass cap on 1" iron pipe, 0.1 ft. above grade.
- A 46" D.Fir snag, bears N.8°15'E., 11.9 ft. to face, with healed face & tag.
- A 36" D.Fir metal covered stump, bears N.35°W., 31.7 ft. to face, with partially visible scribe tag.
- A 13" (6") D.Fir bears N.51°W., 51.0 ft. with healed face.
- A 14" (8") D.Fir bears S.1°E., 16.6' (17.0') with healed face.

Note - Distances to fd. BTs were measured with tape. Trees were red band & face painted. Trees fd. without tags have new tags facing monument.