

PRIMARY CORNER DESCRIPTION Sec. Cor. for 27, 28, 33 and 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Robert Elder and Henry Gile, Deputy Surveyors, under Contract #31 dated April 7, 1853 (DCSO records Vol. 8 Page(s) 3147)

Set post cor. to secs. 27, 28, 33 and 34, from which
 A Laurel 26" dia., bears S.50°E., 106 lks. dist.
 A Y.Oak 24" dia., bears S.67½°W., 57 lks. dist.
 A Y.Oak 18" dia., bears N.57½°E., 47 lks. dist.
 A Y.Oak 11" dia., bears N.31°W., 77 lks. dist.

Douglas Co. Surveyors Office - Milo Godfrey, Deputy - V. Tracy & Mike Stone, crew - Sept. 5, 1963 - C.S. File 49/83-33

Found - Rock 4" x 10" x 14" above ground, rock mkd. with "X" on top, 3 grooves on E. face, 1 groove on S. face, and "33" on SW face.
 48" dead Laurel snag, S.50°E., 70.0 ft. NE side completely burned away, no scribing or old axe marks.
 40" B.Oak, almost completely dead, S.67½°W., 37.6 ft. Tree hollow and NE side completely burned away.

No trace of NE or NW old BTs.
 Set brass cap at cor. alongside rock, mkd:
 County Surveyors Office
 T 24 S R 6 W
 S28|S27
 S33|S34
 1963

New BTs -6" Madrone S.12°E., 59.8 ft. mkd. T24S R6W S34 CS BT
 9" Madrone S.4½°W., 72.4 ft. mkd. T24S R6W S33 CS BT
 12" D.Fir N.60°W., 133.7 ft. mkd. T24S R6W S28 CS BT
 (bottom of blaze 3 ft. above ground)
 No tree available to NE.
 Corner is in E and W fence line on steep West slope, just E. of abandoned mill site.

BLM resurvey by Wayne L. Rogers, Cadastral Surveyor, under Group #969, surveyed April/May 1979 (DCSO records Vol. 42 Page(s) 16488)

The Sec. cor., perpetuated by Godfrey in 1963, monumented with an iron post, 1¼" dia., firmly set, projecting 12" above ground with a 1963 DCSO brass cap from which the remains of the original bearing trees:
 A burned Laurel snag 48" dia., bears S.50°E., 106 lks. dist., no marks visible.
 (Cont. Next Page)

TOWNSHIP 24 RANGE 06 POINT IDENTIFIER # 400200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 27, 28, 33 and 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A B.Oak snag 40" dia., bears S.67½°W., 57 lks. dist., no marks visible.
and the remains of bearing trees mkd. by Godfrey
A Madrone 9" dia., bears S.12°E., 91 lks. dist., with scribe marks 24S R6W S34 CS B visible on open blaze.
A Madrone 14" dia., bears S.4½°W., 110 lks. dist., with scribe marks 4S R6W S33 visible on partially healed blaze.
A sawed Fir stump 18" dia., bears N.60°W., 203 lks. dist., with healed blaze.
and a new bearing tree and a reference monument
An iron post 28" long 2½" dia., set 24" in the ground for a reference monument, bears N.35°E., 20 lks. dist., with brass cap mkd. T24S R6W S27 RM 20 LKS 1979 and an arrow pointing to the corner.
A Madrone 6" dia., bears S.82°W., 28 lks. dist., mkd X BT.
Corner is located in a woven wire fence line, extending E and W.

Fd. Ok by Les Roberts - March 2000 - M134-38