

TOWNSHIP 24 RANGE 06 POINT IDENTIFIER # 400240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 27 and 28

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Robert Elder and Henry Gile, Deputy Surveyors, under Contract #31 dated April 7, 1853 (DCSO records Vol. 8 Page(s) 3148)

-----  
Set ¼ sec. post, from which  
A Y.Oak 12" dia., bears N.68°W., 78 lks. dist.  
A Y.Oak 15" dia., bears N.78 ¾°E., 99 lks. dist.

Survey for L.B. Denny - E. Warner and Lonnie Crawford, crew - Oct. 19, 1910 - Field Book 55 Pg. 43

-----  
Found - 1/4 Post and old BTs, rotted and markings dim. (1853 survey)  
Set Sandstone 8" x 12" x 12" marked 1/4.  
BTs - A W.Oak 11" mkd. ¼S CS bears S.34½°W., 35 lks.  
A Laurel 26" mkd. ¼S CS bears East, 79 lks.

Reported as not fd. - DCSO 9/4/1970 (added 3/28/2017) C.S. File 52/102-19 - Had good line from sec. cor. to south - this area all clearcut & burnt. Also land owner knew nothing of this corner.  
Not Fd, DCSO John Powell & crew, 9/8/1970 (added 3/28/2017) C.S. file 52/102-18 - This area clear cut and had heavy fire in 1950±. No trace of any trees.

BLM resurvey by Wayne L. Rogers, Cadastral Surveyor, under Group #969, surveyed April/May 1979 (DCSO records Vol. 42 Page(s) 16489)

-----  
Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.  
Set an iron post 28" long 2½" dia., 24" in the ground, with brass cap mkd:  
T 24 S R 6 W  
1/4  
S 28 | S 27  
1979  
from which  
A Fir 4" dia., bears S.51½°E., 70 lks. dist. mkd. X BT.  
A Fir 6" dia., bears S.55½°W., 55 lks. dist. mkd. ¼ S28 BT