

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 4

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #577, dated July 18, 1891 (DCSO recs Vol 8 Pg 3177)

Set Fir post, 4 ft. long, 4" sq., 24" in the ground for ¼ sec. cor. mkd. ¼ S on W. face, from which
A Fir 5" dia., bears S.18°E., 11 lks. mkd. ¼ S BT.
A Dogwood 5" dia., bears S.47°15'W., 14 lks. mkd. ¼ S BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, V. Perron, crew - Oct. 6, 1969 - C.S. File 52/102-6

Found - Orig. 5" now 24" Fir, alive, S.18°E., 7.3 ft., shows old scar. Rescribed "¼ S3 CS BT"
Orig. 5" now 16" Dogwood, alive, S.45¼°W., 9.2 ft., previously opened, "T" scribe visible. Open top of lower scar and find "1" reverse.

Set Brass cap at cor. mkd: County Surveyors Office
T 24 S R 6 W
¼ S 4 | S 3
1969

New BT - 13" D.Fir N.62°W., 32.1 ft. mkd. ¼ S4 CS BT.
This corner lies 36 ft. South of creek, 2 ft. wide, course NW.

Fd. OK, May 6, 1982, H. Johnstone, M 92-17

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2314, Surveyed July/Aug. 2010 - (DCSO records Vol. 58 Page(s) 22887)

The ¼ sec. cor. of secs. 3 and 4, perpetuated by the Douglas Co. Surveyor's Office in 1969, monumented with an iron post, 1¼" dia., firmly set, projecting 10" above ground, with a brass cap (properly) mkd.

from which the remains of the original bearing trees
A fir, 32" dia., bears S.18°E., 7.3 ft., with a healed blaze.

A roothole bears S.47¼°W., 9.2 ft., alongside of which is a down, decayed dogwood snag, 11" dia. with a hollow blaze.

and the remains of BTs mkd by the Douglas Co Surveyors Office

A decayed fir stump, size indeterminate. bears N.62°W., 32.1 ft., with no marks visible.

and a new bearing tree

A maple, 13" dia., bears S.33½°W., 24.7 ft., mkd. ¼ S4 BT.
Corner is located 45 ft. S. of a ravine, drains N.70°W., and 190 ft. N. of a spur, slopes N.40°W.