

TOWNSHIP 24 RANGE 06 POINT IDENTIFIER # 440440

PRIMARY CORNER DESCRIPTION Center 1/4 Cor for Sec 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM survey by Wayne L. Rogers, Cadastral Surveyor, under Group #1623, surveyed Sept/Oct. 1991 (DCSO records Vol. 50 Page(s) 19230)

Point for the center ¼ sec. cor. of sec. 15, at intersection with the E. and W. center line.
Set a stainless steel post, 28" long 2½" dia., 24" in the ground with brass cap mkd: T24S R6W
 C 1/4 S 15
 1991

from which
 A Fir 9" dia., bears N.37°E., 33 lks. mkd. C¼ S15 BT
 A Fir 12" dia., bears N.50°W., 14 lks. mkd. C¼ S15 BT.
Deposit a white "DEEP-1" magnetic marker at base of stainless steel post.

Mark Smalley - For: Roseburg Resources - 8/1998 - M 129-12

Found - 1991 Cadastral brass cap on iron pipe.
 9" Fir, N.37°E., 21.8'. Healed.
 13" Fir, N.50°W., 9.2', partly healed.
Scribed- 13" Fir, S.30°W., 9.6', "C¼ BT"
 10" Fir, S.15°E., 10.6' "C¼ BT"

Fd. BC, NE BT down and other 3 BTs stumps, by C. Sweeden, 2/2012 - M163-27

Fd. BC & BTs of record, 9/2018 - Neil Hibbs

Daniel A Renton, Minister-Glaeser Surveying - Garrett Finch & Crew - For: US Department of Interior, BLM - Mean Mustard & Galagher Canyon 1- Task A -Aug. 2023 - M185-5 A-D

Found - 3¼" BLM brass cap (properly mkd), 0.3' above ground from which:
 A north/south barb wire fence bears 2.5' West
 A 9" rotted stump bears S.25°E., 10.3' to side center, mkd. C ¼ BT with nail/washer LS2354 at base of blaze & sign, 9.8' to nail at face (1998)
 A 12" rotten stump bears S.28°W., 9.5' to side center, mkd: C ¼ BT with nail/washer LS2354 at base of blaze & sign, 8.7' to nail at face (1998)
 A 12" snag bears N.45°W., 10.7' with healed blaze and signs (1991)
New - A 23" Cedar bears N.21°W., 30.3' mkd: C ¼ S15 BT
 A 7" Fir bears S.73°E., 18.6' mkd: C ¼ S15 BT
(Set chaining nail at side center, BT signs on front and back and painted red band for existing & new BTs)