

TOWNSHIP 24 RANGE 06 POINT IDENTIFIER # 440600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 10

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #577, dated July 18, 1891 (DCSO records Vol. 8 Page(s) 3172)

-----  
Set Fir post 4 ft. long, 4" sq., 24" in the ground for ¼ sec. cor. mkd. ¼ S on N. face, from which  
A Fir 11" dia., bears S.70°E., 3 lks. dist. mkd. ¼ S BT.  
A Fir 35" dia., bears N.12°45'W., 33 lks. dist. mkd. ¼ S BT.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy, Mike Stone, crew - Oct. 23, 1962 - C.S. File 49/83-32

-----  
Found - Rotten Fir snag N.12 3/4°W., 21.8 ft., good reverse scribing "¼S" on small piece of wood lying at base of snag.  
20" D.Fir S.70°E., 2.0 ft. Tree alive and in good condition.

Set Brass cap at cor. mkd: County Surveyors Office  
T 24 S R 6 W  
¼  $\frac{S\ 3}{S\ 10}$   
1962

Reblazed and scribe:  
20" D.Fir S.70°E., 2.0 ft. mkd. ¼ S10 CS BT.  
New BT - 27" D.Fir N.23°W., 44.1 ft. mkd. ¼ S3 CS BT.  
Corner lies on very steep East slope.

FD OK by Ken Hoffine, April 1996 - M 123-66  
Fd. OK by C. Sweeden, Sept. 2002 - 2002-0038 A & B  
Found OK by K. DeGroot, June 2004 - M146-6