

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 10 and 11

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - Robert Elder and Henry Gile, Deputy Surveyors, under Contract #31 dated April 7, 1853 (DCSO records Vol. 8 Page(s) 3146)

Set ¼ sec. post, from which
A Y.Oak 15" dia., bears S.34°W., 40 lks. dist.
A Y.Oak 12" dia., bears N.60°E., 19 lks. dist.

Howard Johnstone - For: Roseburg Lumber Co. - April 1975, (Filed 3/95) - C.S. File 63/161-20

Set - 1½" Iron rod by single proportion method.

BLM resurvey by Daniel Berry and Charles Akin Cadastral Surveyors, and Glenn Baughman, LS #536 under Group #'s 826 and 856, Surveyed Sept. 1973/Aug. 1975 (DCSO records Vol. 37 Page(s) 15241)

The ¼ sec. cor., established by Roseburg Lumber Co., in 1973, monumented with an iron pipe, 1½" dia., firmly set, projecting 8" above ground.

At the corner point
Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd:
 1/4
 S 10 | S 11
 T 24 S R 6 W
 1973

from which
An Oak 12" dia., bears N.39°E., 111 lks. dist., mkd. ¼ S11 BT.
An Oak 11" dia., bears N.77¼°W., 327 lks. dist., mkd. ¼ S10 BT.
Reset iron pipe alongside iron post.

Ken Hoffine - For: Lone Rock Timber Co. - April 1996 - M 123-66

Found - BLM Brass cap 0.4' above ground set in cement.
18" Oak, bears N.39¼°E., 73.4'. We tagged.
12" down oak, N.77°W., 215.4' to stump hole.
West cedar fence post on hinge side of gate, bears N.51 ¾°W., 15.43'.
Southwest edge of barn bears S.60 ¾°E., 114.8'.
Northwest edge of barn bears S.78½°E., 99.9'.
Corner lies in cow pasture on moderate westerly slope approx. 50' east of gravel road.

continued next page

TOWNSHIP 24 RANGE 06 POINT IDENTIFIER # 500540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 10 and 11

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

Fd. OK by C. Sweeden, Sept. 2002 - 2002-0038 A & B
Found OK by K. DeGroot, June 2004 - M146-6