

TOWNSHIP 24 RANGE 06 POINT IDENTIFIER # 500600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2, 3, 10 and 11

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Robert Elder and Henry Gile, Deputy Surveyors, under Contract #31 dated April 7, 1853 (DCSO records Vol. 8 Page(s) 3146)

Set post cor. to secs. 2, 3, 10 and 11, from which
A Y.Oak 14" dia., bears N.50°E., 20 lks. dist.
A Laurel 26" dia., bears S.5°E., 108 lks. dist.
A Fir 30" dia., bears S.67°W., 68 lks. dist.
A Fir 20" dia., bears N.75°W., 51 lks. dist.

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #577, dated July 18, 1891 (DCSO records Vol. 8 Page(s) 3172)

The sec. cor. to 2, 3, 10 and 11, Post gone; reestablished same by setting Fir post, 4 ft. long, 4" sq., 24" in the ground for corner, mkd. T24S S2 on NE.; R6W S11 on SE.; S10 on SW.; and S3 on NW. faces, with 5 notches on S. and 2 notches on E. edges, from which
An Oak 14" dia., bears N.50°E., 20 lks. dist. mkd. T24S R6W S2 BT.
A Laurel 26" dia., bears S.5°E., 108 lks. dist. mkd. T24S R6W S11 BT.
A Fir 30" dia., bears S.67°W., 68 lks. dist. mkd. T24S R6W S10 BT.
A Fir 20" dia., bears N.75°W., 51 lks. dist. mkd. T24S R6W S3 BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, Milo Godfrey; S.A. Bilow, crew - Aug. 1958 - C.S. File 49/83-14

Found - Old scribed stake at corner.
Orig. Y.Oak N.50°E., 13.2 ft., now stump hole only.
Orig. 26" Laurel S.5°E., 71.3 ft., old face burned out. No scribing found.
No trace of orig. NW BT.
Orig. 30" now 36" Fir snag, S.67°W., 44.9 ft. I open and find good scribing "10"

Set Brass cap at cor. mkd: County Surveyors Office
T 24 S R 6 W
S 3 | S 2
S10 | S11
1958

New BTs -25" R.Fir bears N.25°E., 14.5 ft. scribed S2 T24S R6W CS BT.
23" R.Fir bears N.3°W., 16.0 ft. scribed S3 T24S R6W CS BT.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2, 3, 10 and 11

Alias	Description
Alias	Description
Alias	Description
Alias	Description

30" R.Fir bears S.65°E., 3.5 ft. scribed S10 T24S R6W CS BT.
60" Cedar bears S.42½°W., 85.3 ft. scribed S10 T24S R6W CS BT.

BLM resurvey by Daniel Berry and Charles Akin Cadastral Surveyors, and Glenn Baughman, LS #536 under Group #'s 826 and 856, Surveyed Sept. 1973/Aug. 1975 (DCSO records Vol. 37 Page(s) 15242-43)

The Sec. cor., perpetuated and recorded by Byron in 1958, monumented with an iron post, 2' dia., firmly set, projecting 10" above ground, with 1958 DCSO brass cap from which the remains of the original bearing trees
A root hole, bears N.50°E., 20 lks. dist.
A Laurel stump 30" dia., bears S.5°E., 108 lks. dist., no marks visible on burned blaze.
(Cont. Next Page)

A Fir snag 30" dia., bears S.67°W., 68 lks. dist., with scribe marks 10 visible on partially healed blaze.
A root hole bears N.75°W., 51 lks. dist.
and the remains of bearing trees mkd. by Byron
A root hole bears N.25°E., 22 lks. dist., with a down Fir alongside 27" dia., with healed blaze.
A Fir 34" dia., bears S.55°E., 5 lks. dist., with healed blaze.
A Cedar 48" dia., bears S.42°W., 131 lks. dist., with scribe marks T24S R6W S10 CS BT visible on partially healed blaze.
A root hole bears N.3°W., 24 lks. dist., with a down Fir alongside 25" dia., with scribe marks T24S R6W S3 CS BT visible on open blaze.
and new bearing trees
A Fir 14" dia., bears N.14½°E., 237 lks. dist., mkd. T24S R6W S2 BT.
A Fir 28" dia., bears N.41½°W., 132½ lks. dist., mkd. T24S R6W S3 BT.

Fd. OK by C. Sweeden, Sept. 2002 - 2002-0038 A & B

Found OK by K. DeGroot, June 2004 - M146-6