

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 2 and 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #577, dated July 18, 1891 (DCSO records Vol. 8 Page(s) 3174)

Set Fir post, 4 ft. long, 4" sq., 24" in the ground for ¼ sec. cor. marked ¼ S on N. face, from which

A Fir 20" dia., bears S.67°30'W., 26 lks. mkd. ¼ S BT.

A Fir 24" dia., bears N.50°15'E., 43 lks. mkd. ¼ S BT.

Survey by Wilford N. Haines - For: E.G. Whipple and Harold Woolley - Sept. 1957 - M 5-52

Found - 20" Fir S.67°30'W., 26 lks.
 24" Fir N.50°15'E., 43 lks., dead and down.

Scribed- 12" I.Cedar N.42°30'E., 9.2 ft.

Set and scribed 4" x 4" x 36" Yew post for ¼ corner "Wilford N. Haines Drain, Oregon, #239 Survey Pt."

BLM resurvey by Daniel Berry and Charles Akin Cadastral Surveyors, and Glenn Baughman, LS #536 under Group #'s 826 and 856, Surveyed Sept. 1973/Aug. 1975 (DCSO records Vol. 37 Page(s) 15243)

The ¼ sec. cor., perpetuated and recorded by Haines in 1954, monumented with a wooden post, 3" sq., firmly set, projecting 26" above ground, mks ¼ S2 on N. face and ¼ S11 on S. face, from which the remains of the original bearing trees:

A Fir 20" dia., bears S.67½°W., 26 lks. dist., with scribe marks ¼ S visible on open blaze.

A root hole bears N.50¼°E., 43 lks. dist., with a down and decayed Fir alongside 24" dia., no marks visible.

and a bearing tree mkd. by Haines:

A Cedar 12" dia., bears N.42½°E., 14 lks. dist., with fragmentry scribe marks visible on partially healed blaze.

At the corner point

Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd:

T 24 S R 6 W

1/4 $\frac{S\ 2}{S\ 11}$

1975

Reset wooden post alongside iron post.

Found OK by D. Edwards, May 2002 - M140-13