

TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 100634

PRIMARY CORNER DESCRIPTION E. 1/4 Cor. for Sec. 1 only, T24-8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 8 Page(s) 3224)

Set a post 3½ ft. long, 3" sq., 24" in the ground for ¼ sec. cor., marked ¼ S on W. face from which
A Fir 18" dia., bears N.78°E., 26 lks. dist. mkd. ¼ S BT.
A Fir 18" dia., bears N.50°W., 64 lks. dist. mkd. ¼ S BT.

Douglas Co. Surveyors Office - Jim Byron and crew - July 8, 1971 - C.S. File 49/41 & C.S. File 54/55-24

Looked for not found.
Found old N-S blazes on some burnt stobs. Also, N-S line has been brushed with 9" tree blazed on all four sides at approx. cor. location. Good calls to fit contours on ground. Some very large trees opened to the East of blazed line, these trees too large for orig. BTs. Cor. possibly destroyed by cat work. There is an old clear cut unit to the SW. of the not found corner 1/4 cor.

BLM Dependent resurvey by A. Bert Skeesick, Cadastral Surveyor and Robert H. Browning, Survey Tech, under special instructions and Group No. 2104, surveyed July 2005/Jan. 2006 (DCSO records Vol. 57 Page(s) 22400-1)

Point for the ¼ sec. cor. of sec. 1 only, at proportionate distance. There is no remaining evidence of the orig. cor. At the corner point
Set a stainless steel post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd.

T 24 S
R8W | R7W
¼ |
S1
2005

from which
A fir, 7" dia., bears S.29¼°W., 15.3 ft., mkd. ¼ S1 BT.
A fir, 8" dia., bears N.63¼°W., 31.1 ft., mkd. X BT.
Deposit a magnet in a white plastic case at the base of the stainless steel post.