

TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 140300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 19 and 30

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 8 Page(s) 3217)

-----  
Set ¼ sec. post, from which  
A Fir 12" dia., bears S.60°E., 30 lks. dist.  
An Oak 36" dia., bears N.25°E., 63 lks. dist.

Fd. and used in GL0 survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 8 Page(s) 3272)

H.L. Eppstein, County Surveyor - Wit: N.E. Richardson; Ernie Short - Oct. 21, 1928 - Vol. 3 Page 288

-----  
Drove a Studebaker auto axle for corner, placing same from old Fir BT. Old Oak BT there but down.  
Marked new BTs:  
10" Maple S.77°W., 6.5 lks.  
18" Fir N.8°W., 61 lks.

Douglas Co. Surveyors Office - John M. Powell, W. Penley, crew - Dec. 9, 1970 - C.S. File 49/41-64

-----  
Found - Steel axle at ¼ corner.  
10" now 14" Maple S.77°W., 4.3 ft., tree open, scribe visible "4 S"  
18" D.Fir, now down, N.8°W., 40.3 ft., bark scribe visible "¼" etc.  
DO NOT SET BRASS CAP.  
New BT - 10" D.Fir N.67°E., 78.0 ft. scribed ¼ S19 CS BT.  
Corner lies about 20.0 ft. East of draw, running SE.

BLM Dependent resurvey by A. Bert Skeesick, Cadastral Surveyor and Robert H. Browning, Survey Tech, under special instructions and Group No. 2104, surveyed July 2005/Jan. 2006- (DCSO records Vol. 57 Page(s) 22365-6)

-----  
The ¼ sec. cor. of secs. 19 and 30, remonumented by the Douglas County Surveyors Office in 1928 from orig. evidence no longer in existence, and perpetuated by the Douglas County Surveyors Office in 1970, monumented with a car axle, 1¼" dia., firmly set, projecting 3" above ground, with flange, 8" dia., on top, with no marks visible, from which the remains of a bearing tree mkd. by the Douglas County Surveyors Office in 1928

A maple, 18" dia., bears S.78¼°W., 4.8 ft., with fragmentary scribe marks visible on an open blaze.  
continued next page

TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 140300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 19 and 30

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

and BT mkd. by the Douglas County Surveyors Office in 1970  
A fir, 30" dia., bears N.69°E., 77.1 ft., with a healed  
blaze.

At the corner point

Reset the existing car axle, 33" long, 27" in the ground,  
with flange down, and over it, set a stainless steel post,  
28" long, 2½" dia., 23" in the ground, with brass cap mkd.

T24S R7W  
¼  $\frac{S\ 19}{S\ 30}$   
2005

David Edwards - For: Roseburg Resources - Aug. 2025 - M185-44  
-----

Found - 31" Fir, bears N.69°E. 77.1 ft.  
24" Maple with partially healed blaze. Bears  
S.78¾°W. 4.8 ft.  
5.5 ft. steep post is set 2 ft. south.