

TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 140400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 18 and 19

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 8 Page(s) 3262)

A Cedar 6" dia., which I mark $\frac{1}{4}$ S on N. side, for $\frac{1}{4}$ sec. cor., from which
 A Fir 12" dia., bears N.58°E., 13 lks. dist. mkd. $\frac{1}{4}$ S BT.
 A Fir 10" dia., bears S.70°E., 4 lks. dist. mkd. $\frac{1}{4}$ S BT.

Douglas Co. Surveyors Office - James Byron, Deputy - S. Bilow, crew - May 20, 1959 - C.S. File 49/41-22

Found - Orig. 10" now 14" R.Fir bears S.70°E., 2.6 ft. I open and find good scribing "S".
 Orig. 12" now 16" R.Fir N.58°E., 8.6 ft., shows good scars. I do not open.

Set Brass cap at cor. mkd: County Surveyors Office

T 24 S R 7 W

$\frac{1}{4}$ $\frac{S}{S}$ $\frac{18}{19}$

1959

New BT - 6" W.Fir bears S.45°W., 31.0 ft. scribed $\frac{1}{4}$ S19 CS BT

Fd. OK, Nov. 20, 1981 by Les Roberts - M 90-12

BLM Dependent resurvey by A. Bert Skeesick, Cadastral Surveyor and Robert H. Browning, Survey Tech, under special instructions and Group No. 2104, surveyed July 2005/Jan. 2006 (DCSO records Vol. 57 Page(s) 22369)

The $\frac{1}{4}$ sec. cor. of secs. 18 & 19, remonumented by the Douglas County Surveyors Office in 1959, monumented with an iron post, 1 $\frac{1}{4}$ " dia., firmly set, projecting 14 ins. above ground, with brass cap (properly) mkd.

from which the remaining orig. bearing tree

 A fir, 24" dia., bears N.58°E., 8.6 ft., with a healed blaze.

and BT mkd. by the Douglas County Surveyors Office in 1959

 A fir, 19" dia., bears S.44 $\frac{1}{4}$ °W., 29.8 ft., with a healed blaze.