

TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 140600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 6 and 7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 8 Page(s) 3265)

Set a sandstone 18x10x8 ins., 14" in the ground for ¼ sec. cor. marked ¼ on N. face, from which
A Fir 24" dia., bears N.19°E., 68 lks. dist. mkd. ¼ S BT.
A cross, cut in bedrock, bears S.53°30'W., 118 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; Clete Putnam, crew - Sept. 1960 - C.S. File 49/41-39

Found - Original corner stone "S" chiseled on N. face.
Also find & on bedrock, S.53½°W., 77.9 ft.
I find rotted stump section that checks brg. & dist. for original NE. BT.

Set brass cap alongside corner stone and marked
County Surveyors office
T 24 S R 7 W

¼ $\frac{S\ 6}{S\ 7}$
1960

New BTs- 12" Cedar bears S.23p°W., 25.7 ft.
15" Hemlock bears N.17°W., 9.0 ft. scribed ¼ S6 CSBT

Survey by Mark Smalley - For: Scott Timber Co. - Sept. 1996
M 125-67

Found - 1960 County BC/IP and stone, scribed "1", stone is crumbling.

23" Hemlock N.17°W., 9 ft., healed.
20" Cedar S.23½°W., 25.7 ft., healed.

New BTs- 12" Hemlock S.46°E., 45.3 ft., "¼ S BT"
25" Hemlock S.6°W., 46.9 ft., "¼ S BT"

BLM Dependent resurvey by A. Bert Skeesick, Cadastral Surveyor and Robert H. Browning, Survey Tech, under special instructions and Group No. 2104, surveyed July 2005/Jan. 2006 (DCSO records Vol. 57 Page(s) 22379)

The ¼ sec. cor. of secs. 6 and 7, remonumented by the Douglas County Surveyors Office in 1960, and perpetuated by Smalley, in 1996, monumented with an iron post, 1¼" dia., firmly set, projecting 18" above ground (alongside of which is the orig. cor. stone, showing 6x9x6" above ground, crumbling, mkd. S on N. face), with brass cap (properly) mkd. from which the remains of BTs mkd. by the Douglas County Surveyors Office continued next page

TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 140600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 6 and 7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A cedar, 27" dia., bears S.23 $\frac{3}{4}$ °W., 26.1 ft., with a healed blaze.
A hemlock, 23" dia., bears N.16 $\frac{3}{4}$ °W., 9.1 ft., with a healed blaze.
and bearing trees mkd. by Smalley
A hemlock, 13" dia., bears S.43 $\frac{3}{4}$ °E., 44.9 ft., with fragmentary scribe marks visible on a partially healed blaze.
A hemlock, 28" dia., bears S.7°W., 46.4 ft., with fragmentary scribe marks visible on a partially healed blaze.

2