

PRIMARY CORNER DESCRIPTION 1/4 cor. for Secs. 17 and 18

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 8 Page(s) 3260)

Set a post, 3 ft. long, 3" sq., 24" in the ground for 1/4 sec. cor. marked 1/4 S on W. face, from which
A Cedar 20" dia., bears N.9°W., 11 lks. dist. mkd. 1/4 S BT
A Yew 12" dia., bears S.54°E., 25 lks. dist. mkd. 1/4 S BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; Clete Putnam, crew - June 5, 1961 - C.S. 49/41-45

Found - Orig. 20" now 44" Cedar, we open and find good scribing "1/4 S" N.9°W., 7.3 ft.
Orig. 12" now down Yewwood, partly rotted, no scribing found, S.54°E., 16.5 ft.

Set Brass cap at cor. mkd: County Surveyors Office
T 24 S R 7 W
1/4 S18 | S17
1961

New BTs- 11" R.Fir bears S.65°E., 24.5 ft. scribed 1/4 S17 CS BT.
Rescribe orig. now 44" Cedar N.9°W., 7.3 ft. 1/4 S18 CS BT.

BLM resurvey by James E. Jelley, Cadastral Surveyor - under Group #889, surveyed Oct. 1975/April 1976 - (DCSO records Vol. 40 Page(s) 16006-07)

The 1/4 sec. cor., perpetuated and recorded by Byron in 1961, monumented with an iron post 1 1/2" dia., loosely set, projecting 18" above ground, damaged by logging operation, with brass cap mkd. in 1961, from which the remains of the original bearing trees:

A sawed Cedar stump 38" dia., bears N.9°W., 11 lks. dist. with scribe marks 4 S visible on open blaze, rescribed by Byron in 1961, with 1/4 S18 C visible on open blaze alongside.

and the remains of a bearing tree mkd. by Byron:
A root hole bears S.66°E., 36 lks. dist., with a down Fir alongside 12" dia., with scribe marks 1/4 S17 CS BT visible on open blaze.

At the corner point
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

1/4
S 18 | S 17
T 24 S R 7 W
1975

(Cont. Next Page)

TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 200440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 17 and 18

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which new bearing trees:
A Fir 19" dia., bears N.38½°E., 109 lks. dist. mkd. ¼ S17
BT.
A Fir 4" dia., bears N.79½°W., 57 lks. dist. mkd. ¼ S18
BT.
Deposit iron post alongside iron post.

BLM Dependent resurvey by A. Bert Skeesick, Cadastral Surveyor and Robert H. Browning, Survey Tech, under special instructions and Group No. 2104, surveyed July 2005/Jan. 2006 (DCSO records Vol. 57 Page(s) 22370)

The ¼ sec. cor. of secs. 17 and 18, monumented with an iron post, 2½" dia., firmly set, projecting 4" above ground, with brass cap (properly) mkd.
from which the remains of an orig. bearing tree
A sawed cedar stump, 25" dia. bears N.9°W., 7.3 ft., with fragmentary scribe marks visible on an opened blaze.
(Rescribed by Byron in 1961)
and bearing trees mkd. by Jelley
A fir, 35" dia. bears N.38½°E., 71.9 ft., with a healed blaze.
A fir, 20" dia. bears N.79½°W., 37.6 ft., with a healed blaze.