

PRIMARY CORNER DESCRIPTION NW 1/16 Sec. 5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM Resurvey by C. Albert White, Cadastral Surveyor and Donald R. Beck, Surveying Technician, Under Group #515, Surveyed June/Oct. 1963 - (DCSO records Vol. 32 Page(s) 13489)

Point for the NW 1/16 sec. cor. of sec. 5, at intersection with the E & W centerline of the NW $\frac{1}{4}$.
Set an iron post, 28" long, 2 $\frac{1}{2}$ " dia., 24" in the ground, with brass cap marked: NW 1/16 S5
1963

from which
A fir, 12" dia., bears N.41°E., 29 lks., mkd: NW 1/16 S5 BT.
A fir, 14" dia., bears N.66°W., 10 lks., mkd: NW 1/16 S5 BT.

Douglas Co. Surveyors Office - Stephen J Flause - Mike Koch - 8/29/2014 - C.S. File 67/41-57

Found - The orig. 1963 monument, a 3 $\frac{1}{4}$ " dia., brass cap (properly mkd) on a 2" I.D. iron pipe is set plumb protruding 5" above ground.
1963 BTs- A fir, 12" dia., now a small distinct root-hole; bears N.41°E., 19.1 ft. (as per rec.)
A fir 14" dia., now a mostly rotted away fir stump 4" in dia., at top and 2 ft tall with evidence of a healed blaze which is opened to find the scribing "NW 1/16 S5 BT". This stump bears N.66°W., 6.6 ft. (as per rec.)
New - A D.Fir" dia. 13 scribed "NW 1/16 S5" "CSBT" on a double blaze; bears S.83°W., 13.9 ft.
A D.Fir" dia. 17 scribed "NW 1/16 S5 CS" "BT" on a double blaze; bears N.35°W., 38.3 ft.
Note - Mostly fallen wire fences run south and east from corner. Monument is on gentle east slope at edge of pasture which is to east and north. SW quadrant is medium age reprod fir.
Compass decl. 15 $\frac{1}{2}$ °E.