

TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 300240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 28 and 29

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 8 Page(s) 3209)

-----  
Set ¼ sec. post, from which  
An Oak 12" dia., bears S.80°W., 55 lks. dist.  
An Oak 24" dia., bears N.1°E., 192 lks. dist.

H.L. Eppstein, County Surveyor - Wit: Rudolph Ritzman; J.C. Clayton; Ernie Short - April 1-3, 1926 - C.S. File 14/36 & Vol. 4 Page 3

-----  
Set a 1/2" x 20" I.P. from old BT, scribe marks plain in sec. 28. Marked new BTs as follows:  
Fir 18", N.17°W., 19 ft.  
Fir 15", S.81°E., 21 ft.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; Clete Putnam, crew - Sept. 1, 1960 - C.S. 49/41-33

-----  
Found - 1/2" I.P. at corner.  
18" now 28" Fir stump, N.17°W., 19.0 ft., good scribing. Eppstein BT.  
SE. BT, now down.  
Set brass cap alongside corner pipe marked:  
County Surveyors Office  
T 24 S R 7 W  
¼ S29 | S28  
1960  
Corner is under 60" Fir tree, down.  
New BTs- 20" R.Fir bears N.57½°W., 110.0 ft. scribed ¼ S29 CS BT.  
20" R.Fir bears N.58½°E., 78.7 ft. scribed ¼ S28 CS BT.

Survey by George Grubb - For: Patricia Cagle - Feb. 1982 - M 91-27

-----  
Corner falls under 60" downed Fir.  
Found - 1" I.P. firmly set, projecting 12" above ground with a 2½" brass cap mkd. in 1960.  
1/2" I.P., rusted, alongside.  
24" W.Oak, the rotted remains of which bears N.1°E., 126.7 ft.  
22" windfallen and rotted D.Fir bears S.81°E., 21.0 ft.  
20" D.Fir snag with scribe marks "¼ S29 CS BT" visible on an unhealed blaze, bears N.57½°W., 110.0 ft. (Cont. Next Page)

TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 300240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 28 and 29

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

20" windfallen D.Fir with scribe marks "¼ S28 CS BT" visible on rotted blaze, bears N.58½°E., 78.7 ft.  
New BTs- 9" W.Fir bears N.24°E., 27.0 ft. scribed "¼ S28 BT" on double blaze.  
11" D.Fir bears N.44°W., 36.3 ft. scribed "¼ S29 BT" on double blaze.

Survey by Mark Smalley - For: Scott Timber Co. - Sept. 1996  
-M 124-27

-----  
Found - DCS0 1960 brass cap and iron pipe.  
28" Fir N.17°W., 19.0 ft., stump. (1926)  
20" Fir N.57½°W., 110.0 ft., snag. (1960)  
18" (?), rec. D.Fir, N.24°E., 27.0 ft., healed. (1982)  
8" Maple S.66°E., 10.0 ft. healed. No record.

Fd. per rec. 10/2023 - B Heichel M183-1