

TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 300400

PRIMARY CORNER DESCRIPTION Sec Cor for 16, 17, 20 and 21

Alias <u>868380</u>	Description <u>M.C. on left bank Umpqua River</u>
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 8 Page(s) 3211)

Set meander post, cor. secs. 16, 17, 20 and 21, from which
An Oak 18" dia., bears S.70°E., 45 lks. dist.
An Oak 24" dia., bears N.15°E., 148 lks. dist.
An Oak 18" dia., bears N.45°W., 38 lks. dist.
A Myrtle 9" dia., bears S.38°W., 51 lks. dist.

F. C. Frear, DCSO - Wit: Gene Richardson; Ted Shellabarge; Jim Wolford - July 7, 1939 - "Old corner book Page 49"

Set 1½" x 36" truck axle with 5½" head, from which a
8" W.Oak bears N.54°W., 37.4 ft.
14" R.Fir bears N.80½°W., 23.5 ft.
12" Ash bears S.24°W., 26.0 ft.
Also orig. 30" W.Oak marks still plain, bears N.15°E., 97.7 ft.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; Clete Putnam, crew - March 1960 - C.S. File 49/41-27

Found - 1½" axle at corner.
14" now 18" Fir N.80½°W., 23.5 ft. This BT now snag
8" now 12" W.Oak shows good scar. I do not open.
NE. and SW. BTs gone.
New BT - 26" W.Oak bears N.5°E., 125.8 ft. scribed S16 T24S
R7W CS BT.

BLM resurvey by James E. Jelley, Cadastral Surveyor - under Group #889, surveyed Oct. 1975/April 1976 - (DCSO records Vol. 40 Page(s) 16001-02)

The Sec. Cor., perpetuated and recorded by Frear in 1939, from original evidence no longer in existence, and further perpetuated by Byron in 1960, monumented with a truck axle 1½" dia., firmly set, buried 14" below the surface of the ground, from which a bearing tree mkd. by Frear:

An Oak 15" dia., bears N.54°W., 56½ lks. dist., with fragmentary scribe marks visible on partially opened blaze.

and a bearing tree mkd. by Byron:

An Oak 28" dia., bears N.5°E., 190½ lks. dist., with fragmentary scribe marks visible on partially opened blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 26" in the ground, with brass cap mkd:

TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 300400

PRIMARY CORNER DESCRIPTION Sec Cor for 16, 17, 20 and 21

Alias 868380 Description M.C. on left bank Umpqua River
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

T 24 S R 7 W
S 17 | S 16
S 20 | S 21
1976

from which a reference monument

An iron post 28" long, 2½" dia., set 24" in the ground, for a reference monument, bears N.9½°W., 48½ lks. dist., with brass cap mkd. T24S R7W S17 RM 1976 and an arrow point to the corner.

No suitable trees available within limits.

Deposit axle and drive an iron bar 72" long, 1½" dia., 70" in the ground, alongside iron post.

Douglas Co. Surveyors Office - Greg Quibell, Deputy - John Powell; Randy Smith, crew - Jan. 12, 1982 - C.S. File 61/30-9

Found - 1976 BLM brass cap, properly marked, buried 18" in ground.

1" shaft with 2½" dia. flat top, along NW. edge of BLM brass cap, buried 16" in ground. This monument is possibly Frear's axle although size is different.

No original BTs were found.

8" now 15" Oak with fragmentary scribing visible in previously opened blaze, bears N.54°W., 37.4 ft.

26" now 28" Oak with fragmentary scribing visible on partially open blaze, bears N.5°E., 127.4 ft. (Rec. 125.8 ft.)

1976 BLM brass cap mkd. "T24S R7W S17 RM 1976" bears N.10°W., 31.9 ft.

Since BLM brass cap is buried deep in the ground along river bank, I SET 1" x 30" I.P. with brass cap marked:

"Douglas Co. Surveyor T24S S17 S16 S20 S21 R7W" also "M.C. 1982", directly over BLM cap. New brass cap protrudes 12" out of ground.

New BTs- 11" Myrtle scribed "T24S R7W S17 CS BT" in double blaze, bears N.62°W., 31.0 ft.

9" Ash scribed "T24S R7W S17 CS BT" in double blaze, bears N.73°E., 26.3 ft.

Sketch in field notes in C.S. File. Corner is tied to State Plane Coord. System.

Fd. OK by C. Sweeden, Sept. 1999 - M133-24

continued next page

Alias <u>868380</u>	Description <u>M.C. on left bank Umpqua River</u>
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch
- Aug. 19, 2014 - C.S. File 67/41-55

-
- Found - A 2½" dia., brass cap (properly mkd) on a 1" I.D. I.P. is set plumb, 14" below ground surface. 1982 The 1939 and 1960 monuments which were set side by side in the 1960 renewal are not searched for. The tops of these monuments would now be approximately 4 ft. below the surface. No evidence of the orig. BTs remains. No evidence of the three 1939 renewal BTs.
 - 1960 - A 26" W.Oak now a fallen, rotted and partly sawn for firewood 24+" Oak with no blaze or scribe remnant seen; bears N.5°E., 127.4 ft. (agrees with 1982 record; original record could be a face measurement)
 - 1976 - A 3½" dia., brass cap (properly mkd) on a 2" I.D. iron pipe protruding 3" above ground. This RM bears N.9½°W., 32.0 ft. (as per record) A metal WP and sign 2½ ft. tall is set 0.8 ft. South of this BC.
 - 1982 - An 11" Myrtle now a 38" dia., myrtle (4 trunks grown together) with a fully healed double blaze on the most easterly trunk; bears N.62°W., 31.9 ft. to 4 trunk C.R.C. (rec. N.62°W., 31.0 ft. is good to base of scribed trunk)
A 9" Ash (species mis-identified) now a 12" dia. Alder with a partially healed double blaze showing rotted faces with no scribing visible. This tree bears N.73°E., 26.3 ft. (as per record)
 - New - The monument is left as found 14" below surface but a metal witness post and sign is set south, 1.0 ft., protruding 2 ft. above ground.
A 6" dia. D.Fir scribed "X" "CSBT" on a double blaze; bears N.32½°E., 21.5 ft.
 - Note - Monument is near north edge of the Umpqua River left bank flood plain in silt sand and is susceptible to washout or burial. An East-West forest road centerline is north approx. 45 ft.
Compass decl. 15½°E.