

TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 400300

PRIMARY CORNER DESCRIPTION Sec Cor for 21, 22, 27 and 28

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCS0 records Vol. 8 Page(s) 3207)

Set post cor. secs. 21, 22, 27 and 28, from which
A Fir 48" dia., bears N.75°W., 46 lks. dist.
A Fir 18" dia., bears S.2°W., 220 lks. dist.
A Fir 24" dia., bears S.15°E., 135 lks. dist.
A Fir 24" dia., bears N.15°E., 95 lks. dist.

Fd. and used in GL0 survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCS0 records Vol. 8 Page(s) 3247)

Douglas Co. Surveyors Office - James Byron, Deputy - April 3, 1957 - C.S. File 47/172

Found - Orig. 24" Fir now 40", S.15°E., 89.1 ft. barks scribed "T24S R7W S27" in good condition.
Found rotted stump 36", S.15°E., 62.7 ft., shows old face but no scribing visible.
Found 5 ft. snag, N.75°W., 29 ft. with bark and face rotted, no scribing visible.
The orig. SW. BT not found.

Set an iron pipe with brass cap at corner point marked:
County Surveyors Office

21 | 22
28 | 27
1957

from which

A 7" R.Fir bears N.56°W., 12.0 ft. scribed S21 CS BT
22" R.Fir bears S.33°W., 54.4 ft. scribed S28 T24S
R7W CS BT.
24" R.Fir bears N.78°E., 78.2 ft. scribed S22 T24S
R7W CS BT.

Douglas Co. Surveyors Office - Vernon Tracey and crew - Nov. 23, 1966 - C.S. File 49/41-59

Found - DCS0 brass cap set and mkd. in 1957.
7" now 10" D.Fir N.56°W., 12.0 ft., nearly healed blaze.

Fir BT to SW., now stump.
NE BT, gone. Original BTs gone.

New BTs- 5" D.Fir S.60°E., 34.9 ft. mkd. S27 CS BT.
5" D.Fir N.85°E., 53.2 ft. mkd. S22 CS BT.

Very recent logging around this corner would account for BTs being destroyed. Corner lies on N. slope approx. 400 ft. West of new logging road.

TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 400300

PRIMARY CORNER DESCRIPTION Sec Cor for 21, 22, 27 and 28

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Survey by Mark Smalley - For: Scott Timber Co. - Sept. 1996
-M 124-27

Found - DCS0 1957 BC/IP and 18" x 12" x 6" stone.
18" Fir N.56°W., 12.0 ft., healed. (1957)
24" Fir N.15°E., 62.7 ft., stump. (Orig. BT)
10" Fir N.85°E., 53.2 ft., healed. (1966)
7" Fir S.60°E., 34.9 ft., healed. (1966)
22" Fir S.33°W., 54.4 ft., stump. (1957)
New BT - 8" Fir N.76°W., 21.3 ft., scribed "S 21 BT"

Fd. OK by D.Edwards, Sept. 1998 - M130-26

Ronald L. Rice, Ward NW - July 30, 2010 - C.S. File 65/69-48

Condition report

Found - 2½" Douglas County brass cap dated 1957 (properly marked) with the following accessories:
21" D.Fir bears N.56°W., 12.0' - healed face
16" D.Fir bears N.85°E., 53.2' - healed face
11" D.Fir bears N.76°W., 21.3' - healed face
9" D.Fir bears S.60°E., 34.9' - healed face
22"x6' D.Fir stump bears S.33°W., 54.4' - bark scribing visible

Note - Corner has steel post adjacent to it. All BTs have red painted bands & yellow tags.