

PRIMARY CORNER DESCRIPTION Sec Cor for 2, 3, 10 and 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 8 Page(s) 3202)

Set post, cor. secs. 2, 3, 10 and 11, from which
A Fir 36" dia., bears N.23°E., 11 lks. dist.
A Fir 24" dia., bears N.80°W., 29 lks. dist.
A Fir 6" dia., bears S.60°E., 26 lks. dist.
A Fir 18" dia., bears S.16°W., 50 lks. dist.

GL0 survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 8 Page(s) 3253) and (3256) and (3278)

(Page 3253)

Intersect E. and W. section line 66 lks. E. of cor. to secs. 2, 3, 10 and 11, which is a post 4" sq., marked T24S S2 on NE.; R7W S11 on SE.; S10 on SW.; and S3 on NW., faces, with 5 notches on S. and 2 notches on E. edges, from which
A Fir 40" dia., bears N.23°E., 11 lks. dist. mkd. T24S R7W S2 BT.
A Fir 10" dia., bears S.60°E., 26 lks. dist. mkd. T24S R7W S11 BT.
A Fir 20" dia., bears S.16°W., 50 lks. dist. mkd. T24S R7W S10 BT.
A Fir 30" dia., bears N.80°W., 29 lks. dist. mkd. T24S R7W S3 BT.

(page 3256)

Intersect N. and S. line, 130 lks. S. of cor. to secs. 2, 3, 10 and 11, at which point;

(this is blank, nothing typed)

(Page 3278)

I destroy C C to secs. 3 and 10, and beginning at cor. to secs. 2, 3, 10 and 11, - - - - -.

Fred Dow - Sept. 1953 - C.S. File 41/233

An old Yew wood post found in place and accepted as the section corner. No witness trees found.

Set 1" x 40" steel shaft and established witness trees; to wit

- A 26" Fir bears S.55°E., 27.3 ft. mkd. BT.
- A 22" Fir bears S.11°45'E., 55 ft. mkd. BT.

(Cont. Next Page)

TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 500600

PRIMARY CORNER DESCRIPTION Sec Cor for 2, 3, 10 and 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A.R. Evans - For: L & H Lumber Co. - Nov. 1954 - C.S. File 41/330

Found steel shaft and 3 BTs:
48" Fir N.23°E., 11 lks. (OBT)
26" Fir S.55°E., 27.1 ft. (Dow)
22" Fir S.11 3/4°E., 55.0 ft. (Dow)

Douglas Co. Surveyors Office - John M. Powell, W. Penley, crew - Dec. 10, 1970 - C.S. File 49/41-67

Found - 1" steel shaft at section corner.
26" now 29" D.Fir S.55°E., 27.3 ft., scribe visible, "B".
22" now 26" D.Fir S.12°W., (Rec. S.11°45'E.) 55.0 ft., scribe visible.
DO NOT SET BRASS CAP.
New BTs- 8" D.Fir N.24°W., 40.8 ft. scribed T24S R7W S3 CS BT
11" W.Fir N.73°E., 35.4 ft. scribed T24S R7W S2 CSBT
Reblazed and rescribed:
26" D.Fir S.12°W., 55.0 ft. scribed T24S R7W S10 CS BT.
Corner lies 8.0 ft. East of N-S fence line.

Fd. OK, July 1980 by Charles Guile - M 79-52
Fd. OK, April 1996 by L. Roberts - M 123-73

BLM Dependent resurvey by Dale Bedell, Cadastral Surveyor, under Group #1728, surveyed May 1994-April 1995 - (DCSO records Vol. 52 Page(s) 19835)

The cor. of secs. 2, 3, 10, & 11, perpetuated by Dow, in 1953, further perpetuated by Evans, further perpetuated by Powell, Deputy County Surveyor, in 1970; monumented with a steel axle, 1" diam., firmly set, projecting 4" above ground, from which the remains of an original bearing tree:
A decayed fir stump, 42" diam., bears N.35°E., 13 lks., no marks visible. (Record, N.23°E., 11 lks.)
and bearing trees mkd. by Dow
A fir, 30" diam., bears S.51°E., 44 lks., with healed blaze.
A fir, 29" diam., bears S.16°W., 84 lks., with healed blaze.
and bearing trees mkd. by Powell
A fir, 18" diam., bears N.73°E., 53 lks., with healed blaze.
continued next page

TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 500600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2, 3, 10 and 11

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

A fir, 20" diam., bears N.24°W., 62 lks., with healed blaze.

At the corner point

Set a stainless steel post, 28" long, 2½" diam., 22" in the ground, with brass cap mkd.

T24S	R7W
S 3	S 2
S 10	S 11
1994	

Deposit a white "DEEP-1" magnetic marker at the base, a steel axle with gear under, and a steel fence post alongside the stainless steel post.