

TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 600240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 25 and 26

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 8 Page(s) 3238)

Set a post 3 ft. long, 3" sq., 24" in the ground for 1/4 sec. cor. marked 1/4 S on W. face, from which
A Fir 14" dia., bears N.54 1/2°E., 33 lks. dist. mkd. 1/4 S BT
A Cedar 10" dia., bears S.89°W., 7 lks. dist. mkd. 1/4 S BT

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S. Bilow, crew - Aug. 4, 1958 - C.S. File 49/41-19

Found - Orig. 14" now 32" Fir, previously opened, good scribing visible "S", bears N.54 1/2°E., 21.8 ft.
Orig. 10" now 24" Cedar S.89°W., 4.6 ft., shows good scar. I do not open.

Set Brass cap at cor. mkd: County Surveyors Office
T 24 S R 7 W
1/4 S26 | S25
1958

New BTs- 14" double Cedar bears N.63°E, 14.8 ft. scribed 1/4 S25 CS BT.
I rescribe orig. S.89°W, 4.6 ft., 24" Cedar "1/4 S26 CS BT"