

TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 600464

PRIMARY CORNER DESCRIPTION M.C. Between Secs. 13 & 14

Alias <u>868670</u>	Description <u>M.C. Left Bank Umpqua River</u>
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 8 Page(s) 3197)

Marked a Myrtle, 10" dia., for meander post, left bank of Umpqua River, from which

A Myrtle, 10" dia., bears S.80°W., 2 lks.

A Cedar, 50" dia., bears S.60°E., 33 lks.

BLM Dependent resurvey by Dale Bedell, Cadastral Surveyor, under Group #1728, surveyed May 1994-April 1995 - (DCSO records Vol. 52 Page(s) 19829-30)

21.305 chs. (N.0°14'E. between secs. 13 & 14 from ¼ sec cor.)
Point selected for the witness cor. to the meander cor. of secs. 13 and 14, on the left bank of the Umpqua River.

Set a stainless steel post, 28" long, 2½" diam., 22" in the ground, with brass cap mkd:

T24S R7W
W C
M C
↑
S 14 S 13
1994

from which

A fir, 18" diam., bears S.35°E., 15 lks., mkd. X BT.

A fir, 20" diam., bears S.3°W., 66½ lks., mkd. X BT.

Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.

24.690 chs.

True point for the meander cor. of secs. 13 & 14, for the left bank of the Umpqua River at proportionate distance; there is no remaining evidence of the original corner. This point is located on the steep sandy bank of the river above the water level, but below the mean high waterline where it is impractical to establish a permanent monument.

25.20

Left bank of the Umpqua River, edge bears N.30°W. & S.30°E., course N.30°W.

Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - July 30, 2014 - C.S. File 67/41-37

Found Ok, flagged and tagged as necessary.

Note - Monument is in high flood plain in older fir maple and oak forest.

Compass decl. 15½°E.