

TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 640400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 24

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 8 Page(s) 3195)

Set 1/4 sec. post, from which
A Fir 15" dia., bears S.40°W., 10 lks. dist.
An Oak 24" dia., bears North, 74 lks. dist.

GL0 survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 8 Page(s) 3268)

The 1/4 sec. cor., which is a post, 3" sq., marked 1/4 S on N. face, from which
A Fir 20" dia., bears S.40°W., 10 lks. dist. mkd. 1/4 S BT.
The other bearing tree being gone, I mark
A Fir 4" dia., bears N.11°E., 23 lks. dist. mkd. 1/4 S BT.

F.C. Frear; J.W. Wolford; P.D. Wolford; Jean Richards - Dec. 7, 1932 - (No record source found, see "old" corner book, Paage 49)

Reset from old BTs by setting 3/4" x 30" I.Pipe and 2" x 3" Cedar stake from which a
36" Fir bears S.40°W., 6.6 ft. This is original BT which I remarked.
Also mark 60" Fir, N.19°E., 47.6 ft.

Douglas Co. Surveyors Office - James Byron, Deputy - S.A. Bilow, crew - April 16, 1959 - C.S. File 49/41-21

Found - 3/4" Iron pipe at corner as recorded by Frear.
36" now 42" Fir, S.40°W., 6.6 ft., measured to face, shows good bark scribing "1/4 S BT".
60" now 66" Fir stump, N.19°E., 47.6 ft., shows good bark scribing "BT".
Set Brass cap alongside 3/4" I.P. & mkd:
County Surveyors Office
T 24 S R 7 W
1/4 S 13
S 24
1959
New BT - 14" R.Fir bears N.49 1/2°E., 65.0 ft. scribed 1/4 S13 CS BT.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 24

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM resurvey by Daniel Berry and Charles Akin Cadastral Surveyors, under Group # 807 Surveyed June/July. 1973 - (DCS0 records Vol. 37 Page(s) 15287)

The ¼ sec. cor., perpetuated by Byron in 1959, monumented with an iron post 1½" dia., firmly set, protruding 10" above ground with brass cap mkd. in 1959, from which the remains of the original bearing trees

A Fir stump 42" dia., bears S.40°W., 10 lks. dist., no marks visible on burned blaze.
and a bearing tree mkd. in 1932

A Fir stump 66" dia., bears N.19°E., 73½ lks. dist., no marks visible on burned blaze.
and a bearing tree mkd. by Byron

A Fir 16" dia., bears N.49½°E., 111½ lks. dist., with healed blaze.
and a new bearing tree

A Fir 7" dia., bears S.67½°W., 46½ lks. dist., mkd. ¼ S24 BT.

Fd. OK, Sept. 5, 1986 by OSHD - C.S. File 63/9-10

Fd. OK, April 1994 by L. Dolan - M 121-64

Fd. OK, Oct. 1995 by D. Bentz - M 123-6

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 12/11/2002 - C.S. File 66/48-19A

Found - 1959 DCS0 brass cap/iron pipe protrudes 7" out of ground.

20" now 42" dia., rotted D.Fir stump bears S.40°W., 6.6 ft. (OBT)

24" now 66" dia., rotted D.Fir stump bears N.19°E., 48.8 ft. (OBT)

14" now 24" dia., 3½ ft. high D.Fir stump bears N.49½°E., 73.6 ft. 1959 opened stump & scribing found "CS"

7" now 25" dia., D.Fir with a fully healed blaze bears S.67½°W., 30.7 (1973)

New - 26" dia., D.Fir double blazed & scribed "¼ S13 CS BT" bears N.71½°W., 28.9 ft.

6" dia., D.Fir double blazed & scribed "¼ S24 CS BT" bears S.70½°E., 57.0 ft.

Corner lies 3' West of N'ly & S'ly fence line and 27' West of center line of dirt Rd.

Compass decl. 17½°E.

Fd. ok by D. Edwards 7/2007 - M153-56