

TOWNSHIP 24 RANGE 08 POINT IDENTIFIER # 200240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 29 and 30

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCS0 records Vol. 8 Page(s) 3369)

Set a post 3½ ft. long, 3" sq., 24" in the ground, for ¼ sec. cor. marked ¼ S on W. face, from which
A Fir 36" dia., bears S.27°E., 69 lks. dist. mkd. ¼ S BT.
A Fir 36" dia., bears N.57°W., 31 lks. dist. mkd. ¼ S BT.

BLM resurvey by C. Albert White;, Cadastral Surveyor and Donald R. Beck, Surveying Technician - under Group #427, Surveyed July/Aug. 1962 - (DCS0 records Vol. 32 Page(s) 13332)

The ¼ sec. cor., determined at record bearing and distance from the remaining original bearing tree:

A Fir 36" dia., bears S.27°E., 69 lks. dist. mkd. with old face on opened blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

¼
S 30 | S 29
T 24 S R 8 W
1962

from which new bearing trees

A Fir 6" dia., bears N.48¾°E., 30 lks. dist. mkd. ¼ S29 BT.

A Fir 12" dia., bears N.76°W., 73 lks. dist. mkd. ¼ S30 BT.

Corner is located on the E. edge of the Bateman Lookout Road.

Survey by Mark Smalley - For: Roseburg Forest Products - July 1995 - C.S. File 65/1-1

Found - BLM brass cap with iron pipe dated 1962.

Stone

36" Fir, S.27°E., 45.5 ft., tree is down.

12" Fir, stump, N.76°W., 48.2 ft., cut low.

New BTs- 12" W.Fir N.70°E., 43.1 ft. scribed ¼ S BT.

5" Chinquapin, S.17°W., 9.2 ft. scribed ¼ S BT.

16" Hemlock, S.33°E., 17.7 ft. scribed ¼ S BT.

4" Fir, N.62°W., 9.2 ft. scribed ¼ S BT.

Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and Jeff Lorsung - 3/19/26 - C.S. File 67/62-28

Found - 3¾" BLM brass cap.

Continued next page

TOWNSHIP 24 RANGE 08 POINT IDENTIFIER # 200240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 29 and 30

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

¼
S 30 | S 29
T 24 S R 8 W
1962

Rotted 12" fir stump N.76°W. 48.2 ft.
27" W. Fir N.70°W. 43.1 ft. nail in face.
26" hemlock S.33°E. 17.7 ft. nail in face.
18" fir N.62°W. 6.5 ft. (Rec. 9.2 ft.) nail in face.
Metal post North edge of cap.

New - 7" chinquapin S.22°W. 10.6 ft. scribed X BT on
double blaze. 3½" mag nail right side center.

Notes - Mon is approx. 40 ft. east of ridge logging road.
Compass decl. 14¼°E.
OCS COORDINATE SYSTEM
COTTAGE GROVE-CANYONVILLE ZONE
N. 226505.715 E. 70990.913