

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 28 and 29

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 8 Page(s) 3355)

-----  
Set a post 3½ ft. long, 3" sq., 24" in the ground, for ¼ sec. cor. marked ¼ S on W. face, from which  
A Fir 18" dia., bears N.53°E., 26 lks. dist. mkd. ¼ S BT  
A Fir 20" dia., bears S.56°W., 98 lks. dist. mkd. ¼ S BT

BLM resurvey by C. Albert White;, Cadastral Surveyor and Donald R. Beck, Surveying Technician - under Group #427, Surveyed July/Aug. 1962 - (DCSO records Vol. 32 Page(s) 13325-26)

-----  
The 1/4 sec. cor., determined at record bearing and distance from the original bearing trees:

- A Fir 28" dia., bears N.53°E., 26 lks. dist. mkd. with old axe marks, healed blaze, and cruiser marks.
- A Fir 34" dia., bears S.56°W., 98 lks. dist., mkd. with a healed blaze and old axe marks.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 22" in the ground, with brass cap mkd:

¼  
S 29 S 28  
T 24 S R 8 W  
1962

from which new bearing trees

- A Cedar 13" dia., bears S.27°E., 53 lks. dist. mkd. ¼ S28 BT.
- A Fir 10" dia., bears S.81°W., 36 lks. dist. mkd. ¼ S29 BT.