

TOWNSHIP 24 RANGE 08 POINT IDENTIFIER # 300640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCS0 records Vol. 8 Page(s) 3364)

Set a post 3½ ft. long, 3" sq., 24" in the ground, for ¼ sec. cor. marked ¼ S on W. face, from which
A Fir 20" dia., bears S.80°W., 16 lks. dist. mkd. ¼ S BT.
A Fir 22" dia., bears S.88°E., 14 lks. dist. mkd. ¼ S BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew
April 28, 1966 - C.S. File 49/84-18

Found - Mound of stone at corner.
Orig. 22" now 22" Fir snag, S.88°E., 9.2 ft., shows "¼" scribe, badly rotted and burned.
Orig. 20" now 20" Fir stump, S.80°W., 10.6 ft. badly burned and rotted. No scribe found.
Set Brass cap at cor. mkd: County Surveyors Office
T 24 S R 8 W
¼ S 5 | S 4
1966
New BTs- 5" D.Fir S.24°E., 14.4 ft. mkd. ¼ S4 CS BT.
5" D.Fir S.27°W., 20.4 ft. mkd. ¼ S5 CS BT.
Corner lies on top of ridge, course N.75°E. and S.75°W.