

TOWNSHIP 24 RANGE 08 POINT IDENTIFIER # 400200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 27, 28, 33 and 34

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCS0 records Vol. 8 Page(s) 3340-41)

Set a post 4 ft. long, 4" sq., 24" in the ground for cor. to secs. 27, 28, 33 and 34 marked, T24S S27 on NE.; R8W S34 on SE.; S33 on SW.; and S28 on NW. faces, with 1 notch on S. and 3 notches on E. edges, from which

A Fir 36" dia., bears N.10°E., 33 lks. dist. mkd. T24S R8W S27 BT.

A Fir 36" dia., bears S.55°E., 17 lks. dist. mkd. T24S R8W S34 BT.

A Hemlock 18" dia., bears S.42°W., 18 lks. dist. mkd. T24S R8W S33 BT.

A Maple 10" dia., bears N.61°W., 95 lks. dist. mkd. T24S R8W S28 BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S. Bilow, crew - May 14, 1958 - C.S. File 49/88-3

Found - Orig. 36" now 42" Fir snag, S.55°E., 11.2 ft., has open face, some scribing visible "S".

Orig. NE. BT, now down.

Orig. SW. BT, standing, shows old face but rotted now.

All check good for bearing and distance.

Corner under 40' long.

Set Brass cap at cor. mkd: County Surveyors Office

T 24 S R 8 W

S 28 | S 27

S 33 | S 34

1958

New BTs- 18" R. Fir bears S.68°W., 21.0 ft. scribed S33 T24S R8W CS BT. This tree scribed high, 5 ft. above ground to top scribing.

5" W. Fir bears N.38°W., 28.7 ft. scribed S28 CS BT.

12" W. Fir bears S.59°E., 15.0 ft. scribed S34 T24S R8W CS BT.

10" Fir bears N.20°W., 6.0 ft. scribed S27 T24S R8W CS BT. This BT scribed high, 7 ft. above ground to top of scribe.

Fd. and used in BLM corner remonumentation by Harold D. Corbin, Cadastral Surveyor, under Group #'s 350 and 427, Surveyed June 1959 - (DCS0 records Vol. 30 Page(s) 12609-10)

(Cont. Next Page)

TOWNSHIP 24 RANGE 08 POINT IDENTIFIER # 400200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 27, 28, 33 and 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - L.E. Monrean; Vic Cangie - April 23, 1975 - C.S. File 57/21-11

Found - Brass cap set by DCSO in 1958, properly marked.
34" D.Fir, windfall, lies directly over cap, tree lies in a southerly direction.
18" now 19" Fir now uprooted, bears (lies approx.) S.68°W., 21.0 ft. blazed 5 ft. above ground level.
5" now 8" W.Fir bears N.38°W., 28.7 ft., blazed and tagged.
10" now 15" Fir, bears N.20°W., 6.4 ft. (Rec. 6.0 ft.), blazed 7 ft. above ground and tagged.
12" W.Fir snag, bears S.62°E., 15.0 ft. (Rec. S.59°E.). Face rotted out, tagged.
New BTs- 10" W.Fir bears S.24°W., 20.1 ft. scribed S33 T24S R8W CS BT.
12" Fir bears S.77°E., 53.9 ft. scribed S34 T24S R8W CS BT.

David Edwards - For: Seneca Jones Tbr Co - 3/2005 - M 147-35

Found - Brass cap
All previous BTs gone
New - 7" Fir, N.37°E., 41.38' S27 BT"
10" Fir S.70°E., 13.95' S34 BT"
11" Fir N.61°W., 55.60' S28 BT"
Set 6 foot steel post 2' South

Fd. as per M147-35 12/2016 by D. Edwards, C.S. File 65/94-7