

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 21 and 22

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 8 Page(s) 3345)

Set a post 3½ ft. long, 3" sq., 24" in the ground, for ¼ sec. cor. marked ¼ S on W. face, from which
A Fir 40" dia., bears East, 84 lks. dist. mkd. ¼ S BT.
A Fir 36" dia., bears S.75°W., 47 lks. dist. mkd. ¼ S BT.

BLM resurvey by C. Albert White;, Cadastral Surveyor and Donald R. Beck, Surveying Technician - under Group #427, Surveyed July/Aug. 1962 - (DCSO records Vol. 32 Page(s) 13322)

The ¼ sec. cor., determined at record bearing and distance from the original bearing trees:

A rotted Fir stump 40" dia., bears East, 84 lks. dist., no marks remaining.

A Fir 42" dia., bears S.75°W., 47 lks. dist., mkd. with old axe marks and face on opened blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 22" in the ground, with brass cap mkd:

¼
S 21 S 22
T 24 S R 8 W
1962

from which new bearing trees:

A Fir 13" dia., bears S.32½°E., 120 lks. dist. mkd. ¼ S22 BT.

A Fir 10" dia., bears S.50¼°W., 52 lks. dist. mkd. ¼ S21 BT.