

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 2 and 3

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 8 Page(s) 3338-39)

Set a post 3½ ft. long, 3" sq., 24" in the ground, for ¼ sec. cor. marked ¼ S on W. face, from which
A Fir 20" dia., bears S.42°E., 20 lks. dist. mkd. ¼ S BT.
A Fir 15" dia., bears N.73°W., 47 lks. dist. mkd. ¼ S BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew
May 2, 1969 - C.S. File 54/55-4

Found - Orig. 20" now 27" Fir S.42°E., 13.2 ft., alive, shows good axe scar.
Orig. 15" now 30" Fir N.73°W., 31.0 ft., alive, shows ¼ S scribe.

Set Brass cap at cor. mkd: County Surveyors Office
T 24 S R 8 W
¼ S 3 | S 2
1969

New BTs- 8" Hemlock N.17°E., 13.3 ft. mkd. ¼ S2 CS BT.
9" D.Fir S.73°W., 25.9 ft. mkd. ¼ S3 CS BT.
Corner lies on steep westerly slope 300 ft. E. of creek, course S.

Ron Quimby - Crew: N. Fromdahl & J. Ogden - 6/2019 - C.S. File 65/102-55

Found - DCSO brass cap (properly mkd)
34" Fir stump S.42°E., 13.2 ft. good scar.
44" Fir N.73°W., 31.0 ft. vis. scar
16" down hemlock N.17°E., 13.3 ft.
18" D.Fir S.73°W., 25.9 ft. good scar.
New - 10" Fir N.61°E., 15.2 scribed ¼ S2 BT
5' alum post 5 ft south
Note - Compass decl. 15½°E.