

TOWNSHIP 24 RANGE 08 POINT IDENTIFIER # 600200

PRIMARY CORNER DESCRIPTION Sec Cor for 25, 26, 35 and 36

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 8 Page(s) 3291)

Set post cor. secs. 25, 26, 35 and 36, from which
A Fir 18" dia., bears S.80°E., 42 lks. dist.
A Fir 18" dia., bears N.85°E., 52 lks. dist.
A Fir 60" dia., bears N.73°W., 35 lks. dist.
A Chinquapin 6" dia., bears S.25°W., 28 lks. dist.

Fd. and used in GL0 Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 8 Page(s) 3316)

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S. Bilow, crew - May 1, 1958 - C.S. File 49/84-3

Found - Orig. 18" now 32" R.Fir, S.80°E., 27.7 ft. I open and find good scribing "8"
Orig. 18" now 32" R.Fir N.85°E., 34.3 ft., shows good scars. I do not open.
Rotted base of large Fir that checks bearing and distance for original SW. BT.
No trace of orig. 6" Chinquapin found.

Set Brass cap at cor. mkd: County Surveyors Office

T 24 S R 8 W
S 26 | S 25
S 35 | S 36
1958

New BTs- 10" Hemlock bears N.72°W., 27.2 ft. scribed S26 T24S R8W CS BT.
7" W.Fir bears S.51°E., 18.7 ft. scribed S36 T24S R8W CS BT.
4" R.Fir bears West, 19.6 ft. scribed S35 CS BT.
16" Cedar bears N.75°E., 42.0 ft. scribed S25 T24S R8W CS BT.

Fd. and used in BLM Resurvey by Dale T. Bedell, Cadastral Surveyor, under Group #1241, Surveyed April/May 1986 - (DCSO records Vol. 47 Page(s) 18122)

Found OK by M.Smalley, Jan. 1999 - M131-12

Ronald L. Rice, Ward NW - Dec. 10, 2008 - C.S. File 65/63-39

Found - 3" brass cap dated 1958
41" D.Fir bears N.85°E., 34.3' - healed face
37" D.Fir bears S.80°E., 27.7' - healed face
19" W.Fir bears S.51°E., 18.7' - healed face cont.

TOWNSHIP 24 RANGE 08 POINT IDENTIFIER # 600200

PRIMARY CORNER DESCRIPTION Sec Cor for 25, 26, 35 and 36

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Note - 15" D.Fir bears West 19.6' - healed face
23" Hemlock bears N.72°W., 27.2' - healed face
25" Incense cedar bears N.75°E., 42.0' - healed face
Corner has alum. post adjacent to it. All BTs have red painted bands & yellow tags.

BLM Dependent resurvey by A. Bert Skeesick, Cadastral Surveyor, under Group No. 2102, surveyed May 2005 - Jan. 2006 - (DCSO records Vol. 56 Page(s) 22311 & Plat T24-8 2011)

The cor. of secs. 25, 26, 35, & 36, monumented with an iron post, 1¼" dia., firmly set, projecting 12" above ground, with brass properly mkd.

from which the remaining orig. BTs
A fir, 41" dia., bears N.85°E., 35.0 ft. with a healed blaze.

A fir, 38" dia., bears S.80°E., 27.7 ft. with a healed blaze.

A decayed fir stump, size indeterminate, bears N.73°W., 25.1 ft. with no marks visible.

and BTs mkd. by the DCSO in 1958, reported by Bedell

A cedar, 27" dia., bears N.73½°E., 42.9 ft., with a healed double blaze. (Rec. N.75°E.)

A fir, 20" dia., S.51°E., 18.8 ft. with a healed double blaze.

A fir, 15" dia., bears West, 19.8 ft. with a healed double blaze.

A hemlock, 22" dia., N.72°W., 27.4 ft. with a healed double blaze.

and BT mkd. by person(s) unknown.

A fir, 21" dia., bears N.44¼°E., 28.0 ft. with a healed blaze.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 8/4/2021 (Filed 4/7/2022) - C.S. File 67/51-30 - See also C.S. 67/51-27 pg 1/13

Lat: 43°26'50.51" N Long: 123°36'19.09" W