

TOWNSHIP 24 RANGE 08 POINT IDENTIFIER # 600300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 23, 24, 25 and 26

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 8 Page(s) 3292-93)

Marked a Cedar 6" dia., for cor. secs. 23, 24, 25 and 26, from which

- A Hemlock 18" dia., bears S.40°E., 15 lks. dist.
- A Fir 20" dia., bears N.75°E., 18 lks. dist.
- A Fir 6" dia., bears S.10°W., 55 lks. dist.
- A Maple 6" dia., bears N.15°W., 15 lks. dist.

GL0 Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 8 Page(s) 3317-18)

I go to the sec. cor., which I find nearly obliterated, only the stump of the NE. tree is left standing with indistinct marks. I destroy all trace of the old cor. and re-establish same as follows:

Set a post 4 ft. long, 4" sq., 24" in the ground, marked T24S S24 on NE.; R8W S25 on SE.; S26 on SW.; and S23 on NW. faces, with 2 notches on S. and 1 notch on E. edges, from which

- A Fir 48" dia., N.35°E., 49 lks. dist. T24S R8W S24 BT.
- A Fir 48" dia., S.45°E., 40 lks. dist. T24S R8W S25 BT.
- A Fir 24" dia., bears S.6°W., 54 lks. dist. mkd. T24S R8W S26 BT.
- A Cedar 12" dia., bears N.11°W., 36 lks. dist. mkd. T24S R8W S23 BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S. Bilow, crew - May 1, 1958 - C.S. File 49/84-2

Found all four of Chandler's BTs. All alive and in good condition. The NE. and NW. BTs have open faces and good scribing. All check bearings and distances. Chandler apparently used slope distances.

Set Brass cap at cor. mkd: County Surveyors Office

T	24	S	R	8	W
	S	23		S	24
	S	26		S	25
				1958	

I use same BTs, measurements horizontal & to center of tree:

- 22" Cedar N.9°W., 20.7 ft.
- 60" R.Fir N.35°E., 28.1 ft.
- 60" R.Fir S.40°E., 23.4 ft.
- 36" R.Fir S.5°W., 30.2 ft.

continued next page

TOWNSHIP 24 RANGE 08 POINT IDENTIFIER # 600300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 23, 24, 25 and 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Found OK by R. Rice, June 2003 - M142-47

BLM Dependent resurvey by A. Bert Skeesick, Cadastral Surveyor, under Group No. 2102, surveyed May 2005 - Jan. 2006 - (DCSO records Vol. 56 Page(s) 22311 & Plat T24-8 2011)

The cor. of secs. 23, 24, 25, & 26, remonumented by the DCSO in 1958, monumented with an iron post, 1¼" dia., firmly set, projecting 8" above ground, with brass cap (properly) mkd. from which the remains of BTs mkd. by Chandler

A sawed fir stump, 55" dia., bears N.35°E., 28.3 ft., with a healed blaze. (Rec. 32.3 ft.)

A fir, 69" dia., bears S.45°E., 22.9 ft., with a healed blaze. (Rec. 26.4 ft.)

A fir, 37" dia., bears S.6°W., 28.9 ft. with a healed blaze. (Rec. N.11°W., 223.8 ft.)

A cedar, 33" dia., bears N.8¼°W., 20.5 ft. with a healed blaze. (Rec. N.11°W., 23.8 ft.)

and new BT

A fir, 22" dia., bears N.64°E., 61.8 ft., mkd: T24S R8W S24 BT.