

TOWNSHIP 24 RANGE 08 POINT IDENTIFIER # 600700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1 & 2, (North)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 6 Page(s) 2542)

Set a post 4½ ft. long, 4" sq., 24" in the ground for cor. to secs. 1 and 2 marked T24S S1 on SE.; and R8W S2 on SW. faces, with 1 notch on E. and 5 notches on W. edges, from which
A Fir 10" dia., bears S.17°E., 74 lks. dist. mkd. T24S R8W S1 BT.
A Fir 42" dia., bears S.51°W., 119 lks. dist. mkd. T24S R8W S2 BT.
A Fir 20" dia., bears N.69°W., 103 lks. dist. mkd. T24S R8W BT.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Mike Stone & Mike Stone, Jim Halterman, crew - March 2, 1964 - C.S. File 49/49-14

Measured West 215.2 ft. (3.26 chs.) from cor. secs. 35 and 36, T23S R8W, as determined from old bearing trees. Found 4 BTs facing this point. BTs bear no similarity to trees called for at this corner in govt. field notes. Trees found as follows:
22" D.Fir N.4°W., 11.4 ft., opened by BLM, old scribing visible on old face.
22" D.Fir S.69°E., 24.8 ft., opened by BLM, scribing visible on old face.
Ring count on these two trees show correct age.
Small Fir snag, 10" when mkd., old face shows scribing "T24 R8W"
32" D.Fir N.32°E., 20.9 ft., shows very plain axe scar facing cor., not opened
At 215.2 ft. W. of corner to secs. 35 & 36, Set Iron Pipe with brass cap mkd: County Surveyors Office 1964 T24S R8W S2|S1.
New BTs- 14" D.Fir S.77½°E., 21.7 ft. mkd. T24S R8W S1 CS BT
38" D.Fir S.37°W., 35.0 ft. mkd. T24S R8W S2 CS BT.

BLM Dependent resurvey by A. Bert Skeesick, Cadastral Surveyor and Robert H. Browning, Survey Tech, under special instructions and Group No. 2104, surveyed July 2005/Jan. 2006 (DCSO records Vol. 57 Page(s) 22406)

The cor. of secs. 1 & 2, on the N. bdy of the Tp., remonumented by the Douglas County Surveyors Office in 1964, monumented with an iron post, 1¼" dia., firmly set, projecting 8" above ground, with brass cap (properly) mkd.
continued next page

TOWNSHIP 24 RANGE 08 POINT IDENTIFIER # 600700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1 & 2, (North)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which the remains of BTs mkd. by person(s) unknown, reported by the Douglas County Surveyors Office
A roothole bears N.9½°E., 13.5 ft., with fallen fir trunk, 16" dia., lying alongside, scribe marks T23 8W S35 visible on a decayed blaze.
A roothole bears N.33¾°E., 22.5 ft., with fallen fir trunk, 35" dia., lying alongside, no marks visible.
A roothole bears S.69°E., 24.7 ft., with fallen fir trunk, 14" dia., lying alongside, no marks visible.
and BTs mkd. by the Douglas County Surveyors Office
A roothole bears S.77¾°E., 21.9 ft., with fallen fir trunk, 16" dia., lying alongside, scribe marks 24S R8W S1 C visible on a decayed blaze.
A sawed fir stump, 33" dia., bears S.38¾°W., 34.3 ft., with scribe marks 24S R8W S2 visible on a decayed blaze
and new bearing trees
A fir, 12" dia., bears S.45½°E., 25.7 ft., mkd. T24S R8W S1 BT.
A fir, 7" dia., bears S.73°W., 9.9 ft., mkd T24S R8W S2 BT

Ron Quimby - Crew: N. Fromdahl & J. Ogden - 5/2019 - C.S. File 65/102-51

Found - DCS0 brass cap (properly mkd)
33" Fir stump S.38¾°W., 34.3 vis. scribe.
14" Fir S.45½°E., 25.7 ft. vis. scribe.
9" Fir S.73°W., 9.9 ft. vis. scribe.
16" down Fir S.77¾°E., 21.9 vis. scribe.
New - 13" D.Fir S.11°W., 27.9 ft. scribed T24S R8W S2 BT.
Steel post 2' west & 2' south.
Note - Compass decl. 15½°E.

DCS0 GPS - 8/2021 - added 12/29/2021 - C.S. File 67/51-27
Lat: 43°31'09.64" N Long: 123°36'18.31" W