

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 1 and 12

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 8 Page(s) 3324)

Set a post 3½ ft. long, 3" sq., 24" in the ground, for ¼ sec. cor. marked ¼ S on N. face, from which
A Fir 6" dia., bears N.32°W., 14 lks. dist. mkd. ¼ S BT.
A Fir 12" dia., bears S.4°E., 55 lks. dist. mkd. ¼ S BT.

Douglas Co. Surveyors Office - John M. Powell, W. Penley; J. Heritage, crew - July 8, 1971 - C.S. File 54/55-23

Found - 8" D.Fir stob, N.32°W., 9.8 ft. BLM had opened same to find scribe "BT"

Ring count of about sixty years and tree being dead for quite some time, I believe to be old enough for 1894 survey. Also call on spring branch of 250.0 ft. hits very good. No trace of other BT due to logging.

Set Brass cap at cor. mkd: County Surveyors Office

T 24 S R 8 W

¼ S 1

S 12

1971

New BTs- 6" D.Fir N.16°W., 12.5 ft. scribed ¼ S1 CS BT.

8" D.Fir S.26°E., 103.6 ft. scribed ¼ S12 CS BT.

BLM Dependent resurvey by A. Bert Skeesick, Cadastral Surveyor and Robert H. Browning, Survey Tech, under special instructions and Group No. 2104, surveyed July 2005/Jan. 2006 (DCSO records Vol. 57 Page(s) 22408-9)

The ¼ sec. cor. of secs. 1 & 12, remonumented by the Douglas Co. Surveyors Office in 1971 from orig. evidence no longer in existence, monumented with an iron post, 1¼" dia. firmly set, projecting 12" above ground, with brass cap (properly) mkd from which bearing trees mkd. by the Douglas County Surveyors Office

A fir, 23" dia., bears S.26¾°E., 102.7 ft., with a healed blaze.

A fir, 20" dia., bears N.15°W., 12.4 ft., with a healed blaze.