

PRIMARY CORNER DESCRIPTION Sec. Cor. for 12 & 13 only, (East)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 8 Page(s) 3222)

Set a post 4 ft. long, 4" sq., 24" in the ground for cor. to secs. 7, 12, 13, and 18, marked T24S S7 on NE.; R7W S18 on SE.; R8W S13 on SW.; and S12 on NW. faces, with 4 notches on S. and 2 notches on N. edges, from which

 A Cedar 8" dia., bears N.70°E., 8 lks. dist. mkd. T24S R7W S7 BT.

 A Fir 24" dia., bears S.30°E., 92 lks. dist. mkd. T24S R7W S18 BT.

 A Cedar 60" dia., bears S.15°W., 90 lks. dist. mkd. T24S R8W S13 BT.

 A Fir 24" dia., bears N.20°W., 16½ lks. dist. mkd. T24S R8W S12 BT.

GL0 survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 8 Page(s) 3231 and 3263 and 3278)

(Page 3231 and 3263)
 Found corner as described above)
 (Page 3278)
 I obliterate marks on cors. established by Deputy Chandler referring to secs. for which closing cors. stand. (June 18, 1896)

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; Clete Putnam, crew - July 15, 1960 - C.S. File 49/41-29

Found - Fir stump now 38", N.20°W., 10.9 ft. Stump has been opened and plain scribing "BT" visible. Ring count shows about 60 years growth outside of old face. Old face shows tree to have been about 24" when scribed.

 Cedar 21", bears N.70°E., 5.3 ft. Has been opened and old axe smoothed face visible inside at approx. 8". Scribing probably destroyed when closing corner secs. 7 and 18 was set.

 Position for SE. and SW. BTs fall in logged road. No trace found of either. Corner falls correct dist. South of CC.

Set Brass cap at cor. mkd: County Surveyors Office

	S 12	T24S
R8W	S 13	R7W
	1960	

(Cont. Next Page)

TOWNSHIP 24 RANGE 08 POINT IDENTIFIER # 700500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 12 & 13 only, (East)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>New BTs- 16" R.Cedar S.24°W., 84.3 ft. mkd T24S R8W S13 CS BT 17" R.Cedar N.47°W., 55.8 ft. mkd T24S R8W S12 CS BT</p>
<p>Ronald L. Rice, Ward NW - Sept 2010 - C.S. File 65/69-54 ----- Found - 2½" Douglas Co Surveyor's Office brass cap dated 1960 with the following accessories: 39" W.Red cedar bears N.70°E. 5.3' open, rotted face 36" W.Red cedar bears S.24°W. 84.3' - healed face 36" W.Red cedar bears N.47°W. 55.8' - healed face 38" rotted D.Fir stump bears N.20°W. 10.9' - rotted face New - 21" D.Fir bears S.66°W., 38.0' - blazed, scribed "T24S R8W S13 BT" Note - Corner has steel Post adjacent to it. All BTs have red painted bands and yellow tags. Compass decl. 17°E.</p>
<p>BLM Dependent resurvey by A. Bert Skeesick, Cadastral Surveyor and Robert H. Browning, Survey Tech, under special instructions and Group No. 2104, surveyed July 2005/Jan. 2006 (DCSO records Vol. 57 Page(s) 22394-5) ----- The cor. of secs. 12 and 13 only, remonumented by the Douglas County Surveyors Office in 1960, monumented with an iron post, 1¼" dia., firmly set, projecting 16" above ground, with brass cap (properly) mkd. from which the remains of the orig. bearing trees A cedar, 40" dia., bears N.70°E., 5.3 ft., with no marks visible on an opened blaze. A decayed fir stump, 38" dia., bears N.20°W., 10.9 ft., with no marks visible. and bearing trees mkd. by the Douglas County Surveyors Office A cedar, 34" dia., bears S.22½°W., 84.0 ft., with a healed blaze. A cedar, 36" dia., bears N.47¼°W., 55.9 ft., with a healed blaze.</p>
<p style="text-align: right;">2</p>