

PRIMARY CORNER DESCRIPTION Cor. Secs. 15, 16, 21, & 22

| Alias | Description |
|-------|-------------|
| | |
| | |
| | |
| | |

GLO retracement by Levi C. Walker, Deputy Surveyor, under special instructions, dated Aug. 23, 1905, independent of but in connection with his contract # 763, dated June 20, 1905 - (DCSO records Vol. 8 Page(s) 3437-8)

Set a hemlock post, 3 ft. long, 4" sq. 24" in the ground, for cor. of secs. 15, 16, 21, & 22, mkd:
T24S S15 on NE; R9W S22 on SE; S21 on SW; and S16 on NW face, with 3 notches on S & E edges, from which

- A fir, 40" dia. bears N.1°E., 53 lks. mkd: T24S R9W S15 BT
- A fir, 28" dia. bears S.35°E. 52 lks. mkd: T24S R9W S22 BT
- A fir, 40" dia. bears S.11°W. 11 lks. mkd: T24S R9W S21 BT
- A fir, 30" dia. bears N.43½°W. 50 lks mkd: T24S R9W S16 BT

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - J. Heritage & V. Perron - Feb/March 1968 - C.S. File 54/55-16

Found - Orig. 40" now 50" Fir, alive, S.11°W., 7.3 ft. shows good scar. Do not open.
Orig. 30" now 24" Fir snag, N.43½°W., 33.0 ft. open & find scribe.

Set - Orig. NE & SE BTs, now stumps, down & out of place.
Brass cap at cor. mkd: County Surveyors T24S R9W
Office S 16 | S 15
1968 S 21 | S 22

New BTs- 18" Hemlock N.42°E. 18.3 ft. mkd: T24S R9W S15 CS BT
18" Hemlock S.67°E. 27.4 ft. mkd: T24S R9W S22 CS BT
15" Hemlock S.43°W. 28.8 ft. mkd: T24S R9W S21 CS BT
10" Hemlock N.25°W. 26.4 ft. mkd: T24S R9W S16 CS BT

Note - This corner lies 60 ft. south of road.

Tony Hostetter - For: Weyerhaeuser Co. - Sept. 2015 - C.S. File 65/89-64

Found - 1968 DCS brass cap as described
50" fir stump, OBT, tag, bears S.11°W., 7.3 ft. to center.

New BTs- 24" fir stump, BT tag, bears N.23°E., 48.6 ft. to 6" spike, placed below tag.
12" fir stump, BT tag, bears S.25°E., 7.4 ft. to 6" spike, placed below tag.
18" fir stump, BT tag, bears N.88°W., 12.4 ft. to 6" spike, placed below tag.

Note - New BT bearings determined by hand compass (dec. 18°E)