

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 15 & 16

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO retracement by Levi C. Walker, Deputy Surveyor, under special instructions, dated Aug. 23, 1905, independent of but in connection with his contract # 763, dated June 20, 1905 - (DCSO records Vol. 8 Page(s) 3440)

Set a fir post, 3 ft. long, 5" sq., 24" in the ground, for ¼ sec. cor. marked ¼ S16 on W and 15 on E face; from which
A fir, 24" dia., bears S.27°E., 37 lks., mkd: ¼ S15 BT.
A fir, 30" dia., bears N.85°W., 9 lks., mkd: ¼ S16 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - J. Heritage & V. Perron - Feb/March 1968 - C.S. File 54/55-15

Found - Unrecorded ½" steel pipe set at corner point & old 4"x4" post.
Orig. 24" now 32" fir, alive, S.27°E., 24.4 ft. shows good scar. Do not open.
Orig. 30" now 36" fir, alive, N.85°W., 5.9 ft., open & find scribe marks.
Set - Brass cap at cor. mkd: County Surveyors T24S R9W (Reset Steel pipe Office 1968 ¼ S16|S15 Alongside)
New BTs- 7" Hemlock N.18°W., 29.0 ft. mkd: ¼ S16 CS BT.
5" Chinquapin S.51°E., 27.2 ft. mkd: ¼ S15 CS BT.
Note - This corner lies on moderate south slope on N edge of cut off area.

Tony Hostetter - For: Weyerhaeuser Co. - April 2016 - C.S. File 65/93-22

Found - 2" iron pipe w/brass cap as set by Douglas Co. Surveyor in 1968 (CS 54/55).
Both Baughman BTs are gone.
48" Fir stump, WEYCO tag, listed in Weyerhaeuser Co. records bears; N.87°E., 37.7 ft to center.
New BTs- 13" Fir, BT tag, bears S.66°E., 10.9 ft to 6" spike, placed below tag.
7" Fir, BT tag, bears S.23°W., 6.1 ft to 6" spike, placed below tag.
9" Fir, BT tag, bears S.76°W., 12.7 ft to 6" spike placed below tag.