

TOWNSHIP 25 RANGE 01E POINT IDENTIFIER # 200140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 31 & 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Joseph A Ganong & John G Collins, US Cadastral Engineers under instructions dated March 12, 1921, surveyed May 1927/June 1928 - (DCSO Records Vol. 22 Page(s) 9206)

Set an iron post, 3 ft. long, 1" dia., 6" in the ground to bedrock, surrounded by a mound of stone, 4 ft. base, 2 ft. high, for ¼ sec. cor., with brass cap marked

¼
S 31|S 32
1927

from which

A pine, 12" dia., bears N.14½°E., 461 lks., mkd: ¼ S32 BT.

A fir, 6" dia., bears S.18½°W., 52 lks., mkd: ¼ S31 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage & E. West - March 24, 1967 - C.S. File 52/30-75

Found - 1927 GLO Brass Cap, properly mkd, but almost out of ground.

Reset - Brass Cap in mound of Stone from one Orig. BT
12"?, now 50" Pine, N.14½°E., 304.3 ft., Alive, shows very good scar. Do not open - No trace SW BT

New BT - 12" D.Fir S.34°W., 74.2 ft. mkd. ¼ S31 CS BT.

Note - This corner on precp. SE. rock slope approx. 300 ft. S. of timberline.